

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75690
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 54993 - BRANDON CARDINAL
Address: 830 GOLDEN CANE DR WESTON, FL

33327

Phone: 615-788-4383

Stock Number: 11340 - 2024 CHEROKEE TIMBERWOLF 16ML 5NHTC7624RC113092

VIN: 5NHTC7624RC113092 HIN: SER#: 5NHTC7624RC113092

Mileage: 0

Work Order Comp: 29 JAN 25

Auth. No:

Dealer #:

Warr. Date: 05 JUL 24

Work Order Date: 12 DEC 24

Inv #: 413510

WO # Job # Description JOB INFORMATION

75690 1 CUSTOMER HAD A LEAK FROM THE DISHWASHER AND IT LEAKED ON THE FLOOR AND TORE THE FLOOR UP 1 HR TO PULL LINO BACK AND SEE WHAT IS WRONG AND TAKE PICS
Water damage to the linoleum and floors from the dishwasher
Cut along the edge of the linoleum and unscrew the base trim.
Pulled the linoleum and took pictures of the damage to the floor and the water stain on the linoleum. Received the new linoleum and checked for damage. Rolled out the new linoleum to flatten out. Finished cutting the linoleum pulled the fridge out after unplugging it. Set the fridge in the living area, then pulled up the linoleum. Set the lodge linoleum on the new to try to match a pattern. Set the new linoleum in the kitchen floor and trim to the room size. Applied linoleum glue to the floor in sections. Rolled and pressed the linoleum to work out any wrinkles or air pockets. Let the glue dry, then stapled the trim around the linoleum with batten strips. Added a threshold in between the kitchen and bathroom door. Covered the new floor with plywood to move the fridge back in place and mounted. Did a once over to makes sure trim and accessories were in the proper placement. Had BEN approve of the work.

75690 3 THE LIGHT IN THE SHOWER DOES NOT WORK
Push button to the light
Pushed the button to the fan and it works but the button to the light does not function. Pushed the button to the light and nothing happened such as a clicking. Received the new vent light

Claim : 75690

 WO # Job # Description JOB INFORMATION

 for the shower and checked for damage. Unscrewed the vent from
 the inside and cut the sealer. Unscrewed the vent on the outside
 and disconnected the wires. Put new butyl tape on the new vent
 then screwed the vent to the exterior wall. Connected the wires
 in the inside and mounted the light then tested and added sealer.

75690 2 ZEBRA BLIND BY THE LADDER THE FAR LEFT ONE DOES NOT WORK
 Blind doesn't retract, blind valance
 Took a picture of the blind and tested but the blind would not
 retract. Unscrewed the blind valance from above the blind then
 checked the blind again. Blind now functions. The blind valance
 was sitting on the blind causing not to retract when pushing up
 on the blind. When pulling down on the blind it was more
 struggle, compared to the other blinds.

75690 5 DISHWASHER NOT WORKING
 No water per Bill service call
 Bill had shut off the water to the dishwasher because of a leak.
 When inspecting for the leak found that the factory used the
 wrong size hose. The t valve at the wall and the blue valve
 behind the dishwasher are half inch diameter but the water that
 connects the to valves together was to big causing the hose to
 leak. Let the dishwasher run its cycle with no problems.

 Part No Job# Description PARTS Qty Price Total

 403405 1 BLUE HANDLE WASHER FITTING 1.00 9.11 9.11
 10-0236 1 16051 1/2" x 5' PEX STICK 1.00 4.34 4.34
 F100439530 1 LINOLEUM, 8' X LENGTH - DIAMONDFL 4.00 10.42 41.68
 9129 3 VENT, MAXX AIR 6" DOME FAN W/LED 0.00 0.00 0.00
 9129 3 VENT, MAXX AIR 6" DOME FAN W/LED 1.00 55.06 55.06
 687039 3 (CHEROKEE) SEALANT, GEOCEL 2300 M 1.00 7.48 7.48

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 3.60 170.00 612.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 1.00 170.00 170.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 2.50 170.00 425.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.90 170.00 153.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00

Claim : 75690

```

*****
Lab Code  Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990      2    MISC LABOUR CODE (EXTERNAL)      0.10    170.00    17.00
Z990      2    MISC LABOUR CODE (EXTERNAL)      0.10    170.00    17.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.45    170.00    76.50
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.25    170.00    42.50
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.20    170.00    34.00

```

```

*****
Excode    Job#  Description          EXTRAS          Qty      Price      Total
*****
SS         1    SHOP SUPPLIES              1.00     87.00     87.00
FRT        1    FREIGHT                    1.00    179.53    179.53
FRT        3    UPS-VENT                   1.00     18.36     18.36

```

Parts Total: 117.67
 Labour Total: 1,581.00
 Sublet Total: 0.00
 Extras Total: 284.89

>>>> Claim Total: 1,983.56

Customer Signature: _____

Date: _____