

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75739
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11529 - 2025 APEX 291TBSS 5ZT2CXUB9SS048493
VIN: 5ZT2CXUB9SS048493 HIN: SER#: 5ZT2CXUB9SS048493
Mileage: 0 Work Order Comp: 20 JAN 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 30 DEC 24 Inv #: 413345

WO # Job # Description JOB INFORMATION

75739 8 OUTSIDE GRIDDLE DAMAGED
Scratch on metal area and turn knob is wobbly and crooked...
Replace Grille, Parts Request Submitted.

75739 1 THE TRIM IS LOOSE ABOVE THE SLIDE ROOM
Trim above slideout is not connected on end..
Stapled trim into place.

75739 2 THERE IS A SCRATCH ON THE TRIM UNDER THE BED
Scuff/scratch on trim under master bed..
Magic Erasered white scuff and heated and smoothed out the
scratch.

75739 3 THE BATHROOM DOOR IS HITTING THE DOOR FRAME.
Bathroom door catching on the frame.
Removed jam cover and shaved down the unleveled wood, put jam and
striker back into place.

75739 4 THE SEALER ON THE MIRROR IN THE BATHROOM NEEDS ATTENTION
Sealer spot in Bathroom mirror.
Took some cleaner and scraped with a blade.

75739 5 THE TRIM ON THE SLIDE ROOM CEILING IS LOOSE
Trim on ceiling of slideout is hanging...
Stapled trim into place.

Claim : 75739

WO #	Job #	Description	JOB INFORMATION
75739	6	IN THE BUNK ROOM TRIM IS LOOSE	Trim above bunk is hanging and barely secured, manufacturer staple shot all the way thru the trim... Stapled trim back into place.
75739	7	FURANCE NOT WORKING	No power to Furnace... Removed cover and tested for power from wires, no power at wires. Searched around the Furnace box and discovered power switch was turned off.
75739	9	BEDROOM CLOSET IS DAMAGED	Wall inside closet trim cover was off... Had to remove screws that held closet to wall to put trim cover back over the edge of wall panel and stapled panel back into place and reinstalled mount screws.

Part No	Job#	Description	PARTS	Qty	Price	Total
F100503385	8	GRIDDLE, 18" BASE QUICK CONNECT G		1.00	94.88	94.88

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.10	170.00	17.00
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.10	170.00	17.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.10	170.00	17.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.01	170.00	1.70
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.09	170.00	15.30
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.10	170.00	17.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.10	170.00	17.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.10	170.00	17.00
Z990	9	MISC LABOUR CODE (EXTERNAL)		0.10	170.00	17.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	8	UPS-GRIDDLE CASE		1.00	18.36	18.36

Parts Total:	94.88
Labour Total:	170.00
Sublet Total:	0.00
Extras Total:	18.36

>>>> Claim Total: 283.24

Customer Signature: _____

Date: _____

Claim : 75739

```
*****
Excode      Job#  Description      EXTRAS              Qty      Price      Total
*****
```