

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106	CLAIM STATUS Authorized
BASDEN RV CENTER INC	2175966
DBA AMERICAN RV CENTER	WEB
600 E BASELINE ROAD	CLAIM ORIGIN
EVANSVILLE, IN 47725	ORIGINAL CLAIM ID 5ZT2CXUB9SS048493
USA	VIN
	CHASSIS VIN 0
	MILEAGE 220 / 220A
Labor rate: \$170.00	SITE/WAREHOUSE APTT291TBSS
OWNER INFORMATION	ITEM # 75739
	DEALER RO # 01/18/2025
	CLAIM START DATE 01/01/1900
	CLAIM END DATE

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor Line# 1	Operation Code 30-102-12-00-001096	Operational Description Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-01-18 15:08:07 :: THE TRIM IS LOOSE ABOVE THE SLIDE ROOM THE TRIM IS LOOSE ABOVE THE SLIDE ROOM Stapled trim into place.	
Model#	Dlr Sub Hrs 0.10	Sub Labor Amt \$17.00
Serial#	Appr Hrs 0.10	Appr Labor Amt \$17.00
	Notes	
Labor Line# 2	Operation Code 30-102-12-00-001096	Operational Description Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-01-18 15:09:31 :: THERE IS A SCRATCH ON THE TRIM UNDER THE BED Scuff/scratch on trim under master bed.. Magic Erasered white scuff and heated and smoothed out the scratch.	
Model#	Dlr Sub Hrs 0.30	Sub Labor Amt \$51.00
Serial#	Appr Hrs 0.10	Appr Labor Amt \$17.00
	Notes	
Labor Line# 3	Operation Code 30-101-02-00-001076	Operational Description Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-01-18 15:10:12 :: THE BATHROOM DOOR IS HITTING THE DOOR FRAME. Bathroom door catching on the frame. Removed jam cover and shaved down the unlevelled wood, put jam and striker back into place.	
Model#	Dlr Sub Hrs 0.30	Sub Labor Amt \$51.00
Serial#	Appr Hrs 0.20	Appr Labor Amt \$34.00
	Notes	
Labor Line# 4	Operation Code 30-100-01-00-001041	Operational Description Mirrored Cabinet Door Frame - Interior/Cabinetry/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-01-18 15:11:36 :: THE SEALER ON THE MIRROR IN THE BATHROOM NEEDS ATTENTION Sealer spot in Bathroom mirror. Took some cleaner and scraped with a blade.	

Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$68.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				

Labor Line# 5

Operation Code	Operational Description			
30-102-12-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code			
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2025-01-18 15:12:35 :: THE TRIM ON THE SLIDE ROOM CEILING IS LOOSE Trim on ceiling of slideout is hanging... Stapled trim into place.				
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				

Labor Line# 6

Operation Code	Operational Description			
30-102-12-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code			
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2025-01-18 15:13:47 :: IN THE BUNK ROOM TRIM IS LOOSE Trim above bunk is hanging and barely secured, manufacturer staple shot all the way thru the trim... Stapled trim back into place.				
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				

Labor Line# 7

Operation Code	Operational Description			
70-170-24-00-002053	Suburban Furnace Door - Appliances/Furnace (Suburban)/Repair/No Tread Code			
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2025-01-18 15:15:28 :: FURANCE NOT WORKING No power to Furnace... Removed cover and tested for power from wires, no power at wires. Searched around the Furnace box and discovered power switch was turned off.				
Model# NA	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial# NA	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				

Labor Line# 8

Operation Code	Operational Description			
20-43-01-00-000833	Cooktop or Grill - Exterior/Exterior Miscellaneous/Replace/No Tread Code			
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2025-01-18 15:16:48 :: OUTSIDE GRIDDLE DAMAGED Scratch on metal area and turn knob is wobbly and crooked... Replace Grille, Parts Request Submitted.				
Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$68.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				
Please do not order the complete grille. You can order just the top.				

Labor Line# 9

Operation Code	Operational Description			
30-102-15-00-003365	Wall Access Panel - Interior/Panels, Ceilings, & Interior Moldings/Repair or Replace/No Tread Code			
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2025-01-18 15:17:44 :: BEDROOM CLOSET IS DAMAGED Wall inside closet trim cover was off... Had to remove screws that held closet to wall to put trim cover back over the edge of wall panel and stapled panel back into place and reinstalled mount screws.				
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00

Notes

Submitted			Approved		
	Labor Amt	\$340.00		Labor Amt	\$170.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$340.00		Total	\$170.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.