



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75739
Promised Date:
21 JAN 25

CUSTOMER WORK ORDER

WO #: 75739

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BJW
Location: 0122 CHECK PREAUTH

Stock #: 11529
Stock Desc: 2025 TT COACHMEN APEX
291TBSS
Chassis #: 5ZT2CXUB9SS048493
Serial #: 5ZT2CXUB9SS048493
Mileage: 0
Licence:

Invoice #:
Date In: 30 DEC 24
Promised: 31 JAN 25
Date Sched:
Completed: 20 JAN 25
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JRK	N/C
Z990	WINTERIZE UNIT	JRK	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Customer #: 1000
BASDEN'S AMERICAN RV,





Job #1 - Warranty

COMPLAINT: THE TRIM IS LOOSE ABOVE THE SLIDE ROOM

CAUSE: Trim above slideout is not connected on end..

CORRECTION: Stapled trim into place.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	17.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00

Subtotal for Job #1: 17.00

Job #2 - Warranty

COMPLAINT: THERE IS A SCRATCH ON THE TRIM UNDER THE BED

CAUSE: Scuff/scratch on trim under master bed..

CORRECTION: Magic Erased white scuff and heated and smoothed out the scratch.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	17.00

Subtotal for Job #2: 17.00

Job #3 - Warranty

COMPLAINT: THE BATHROOM DOOR IS HITTING THE DOOR FRAME.

CAUSE: Bathroom door catching on the frame.

CORRECTION: Removed jam cover and shaved down the unlevelled wood, put jam and striker back into place.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	34.00

Subtotal for Job #3: 34.00

Job #4 - Warranty

COMPLAINT: THE SEALER ON THE MIRROR IN THE BATHROOM NEEDS ATTENTION

CAUSE: Sealer spot in Bathroom mirror.

CORRECTION: Took some cleaner and scraped with a blade.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	1.70
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	15.30

Subtotal for Job #4: 17.00

Job #5 - Warranty

COMPLAINT: THE TRIM ON THE SLIDE ROOM CEILING IS LOOSE

CAUSE: Trim on ceiling of slideout is hanging...

CORRECTION: Stapled trim into place.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00



W/O: 75739
Promised Date: 31 JAN 25

Customer #: 1000
BASDEN'S AMERICAN RV,

Z990	MISC LABOUR CODE (EXTERNAL)	JRK	17.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00

Subtotal for Job #5: 17.00

Job #6 - Warranty

COMPLAINT: IN THE BUNK ROOM TRIM IS LOOSE

CAUSE: Trim above bunk is hanging and barely secured, manufacturer staple shot all the way thru the trim...

CORRECTION: Stapled trim back into place.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	17.00

Subtotal for Job #6: 17.00

Job #7 - Warranty

COMPLAINT: FURANCE NOT WORKING

CAUSE: No power to Furnace...

CORRECTION: Removed cover and tested for power from wires, no power at wires. Searched around the Furnace box and discovered power switch was turned off.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	17.00

Subtotal for Job #7: 17.00

Job #8 - Warranty

COMPLAINT: OUTSIDE GRIDDLE DAMAGED

CAUSE: Scratch on metal area and turn knob is wobbly and crooked...

CORRECTION: Replace Grille, Parts Request Submitted.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	17.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00

Parts

Part #	Description	Qty	Price	Total
10349	GRIDDLE, 18" BASE QUICK CONNECT GAS	1.00	94.88	94.88

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-GRIDDLE CASE	1.00	18.36	18.36

Subtotal for Job #8: 130.24

Job #9 - Warranty

COMPLAINT: BEDROOM CLOSET IS DAMAGED

CAUSE: Wall inside closet trim cover was off...

CORRECTION: Had to remove screws that held closet to wall to put trim cover back over the edge of wall panel and stapled panel back into place and reinstalled mount screws.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Z990

MISC LABOUR CODE (EXTERNAL)

JRK

17.00

Subtotal for Job #9:

17.00

Parts Total: 94.88

Labour Total: 170.00

Sublet Total: 0.00

Extras Total: 18.36

WORK ORDER TOTAL:

283.24

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 20 Jan 2025

W/O: 75739
Promised Date: 31 JAN 25



Customer #: 1000
BASDEN'S AMERICAN RV,

