

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75741
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11522 - 2025 CATALINA 263BHCKLE 5ZT2CARB2SN300959

VIN: 5ZT2CARB2SN300959 HIN: SER#: 5ZT2CARB2SN300959

Mileage: 0 Work Order Comp: 09 JAN 25

Auth. No: Dealer #:

Warr. Date: Work Order Date: 30 DEC 24 Inv #: 413193

WO #	Job #	Description	JOB INFORMATION
75741	6	THE COMPARTMENT DOOR RUBS THE AWNING ARM WHEN OPENING Compartment door rubbing awning arm Adjusted awning arm and resealed nuts to clear compartment door.	
75741	2	THE BATHROOM DOOR IS HITTING THE FRAME. NOTED ON DELIVERY Bathroom door rubbing and not closing Adjusted striker plate, hinges and had to remove plastic door jam and remove caulk from where they put to much and caused it to sweel.	
75741	3	THE POSSITIVE BATTERY CABLE IS TOO SHORT TO REACH THE BATTERY Positive cables to short Removed undercarriage cover and untangled cable. And reinstalled battery box in closer location of cables and zip tied wires together neatly.	
75741	4	THE ENTRY DOOR IS HARD TO CLOSE AND IT FEELS LIKE IT IS IN A BIND Door catching on striker plate and step catch. Adjusted striker plate. Added a spacer to step catch.	
75741	5	UNIT IS NOT SEALED ALL THE WAY AROUND THE WATER HEATER Not sealed around Hot Water Heater Removed loose caulk and recaulked.	
75741	7	THE BEDROOM DOOR IS WARPED Door was warpped/Bbent	

Claim : 75741

 WO # Job # Description JOB INFORMATION

Found that the lower was was not squared with the top. Had to take wall apart and shift the bottom about an inch and put wall back together and adjusted striker plate.

75741 10 OUTSIDE REFER IS MOUNTED WRONG AND HITS THE COMPARTMENT DOOR
 Fridge door scrapping compartment door frame
 Removed mounting hardware and shimmer it up 1/8 inch.

75741 11 THE DRAWER CLOSEST TO THE KITCHEN SINK IS HARD TO OPEN AND CLOSE
 Drawer is dragging somewhere
 Located area dragging, under drawer where it locks to hold closed was dragging bottom of drawer. I adjusted the locker down an 1/8th in to clear drag.

Part No	Job#	Description	PARTS	Qty	Price	Total
420927	6	BLACK PUTTY TAPE 30'		1.00	6.47	6.47
F100359506	6	SILICONE, NEUTRAL CURE SILICONE 1		1.00	12.09	12.09

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.60	170.00	102.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.25	170.00	42.50
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.80	170.00	136.00
Z991	10	MISC LABOUR CODE (INTERNAL)		0.10	170.00	17.00
Z990	11	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00

Parts Total: 18.56
 Labour Total: 433.50
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 452.06

Customer Signature: _____

Date: _____