

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75742
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11534 - 2025 CATALINA SUMMIT SERIES 164BHX 5ZT2CAEC5SK010070
VIN: 5ZT2CAEC5SK010070 HIN: SER#: 5ZT2CAEC5SK010070
Mileage: 0 Work Order Comp: 15 JAN 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 30 DEC 24 Inv #: 413267

WO #	Job #	Description	JOB INFORMATION
------	-------	-------------	-----------------

75742	3	LIGHT SWITCH IN THE BATHROOM NEEDS REWIRED. Light switch wouldn't fit into cover. Removed cover and switch and lined up the switch mount with the cutout in the wall. Put it back together.	
-------	---	--	--

75742	4	NONE OF THE USBS ARE WORKING 15a fuses are blowing that is labeled bedroom All USB ports are not working... pulled all of the USB ports from walls and only 1 out of 4 are able to be pulled from wall, the other 3 are tangled behind GFCI wiring and wire nut connectors can't be fully examined. Removed GFCI plugs and untangled wires and disconnected USB port. Furnace. 4th USB port couldn't be accessed so I had to go on the backside of wall and remove bathroom mirror and cut an access hole as instructed by Ben. Ran thru all the wired connections of USB ports and bedroom light... found the the ground from the Wire leading to the fuse has continuity with the power side of the bedroom light. I have to remove trim and upper panel where light is installed to follow and track down the issue. Had to remove a bunch of staples in both the trim and the panel which is time consuming. Found the switch in the outside compartment that powers the exterior front lights is wired into the same fuse and colors of wires do not match... red/white wire at switch turns to a purple/white at inside USB port. I ran a new power supply wire to complete circuitry and bypassed the wire that was being grounded out. I ran it under bed and into the switch in compartment on the	
-------	---	---	--

Claim : 75742

 WO # Job # Description JOB INFORMATION

 constant power side. Then put everything back together (all areas
 worked on has pictures!).

75742 5 NO OUTSIDE SPEAKERS
 No outside speaker on Bside of radio
 Pulled the radio from wall and checked through the wires where I
 found the negative side of B Speaker unhooked which I connected
 with a new wire terminal.

75742 6 WILL NOT HOLD LP PRESSURE
 Doing my DropTest on LP and losing pressure...
 Sprayed down all connection at Furnace, Water Heater and
 Stovetop... used bubbles 1st then used sniffer and found tiny
 leak on backside of furnace.

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.10 170.00 17.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.50 170.00 85.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 3.00 170.00 510.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 1.00 170.00 170.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.50 170.00 85.00

Parts Total: 0.00
 Labour Total: 901.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 901.00

Customer Signature: _____

Date: _____