

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75745
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11532 - 2025 COUGAR 316RLS 4YDFCGR28S2503116
VIN: 4YDFCGR28S2503116 HIN: SER#: 4YDFCGR28S2503116
Mileage: 0 Work Order Comp: 29 JAN 25
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 30 DEC 24 Inv #: 413515

WO # Job # Description JOB INFORMATION

75745 5 THE SCREEN IN THE BATHROOM HAS DIECOR ON IT
Roof vent Screen has dicor on it
I took pictures and filled out parts requests 1-17-25

75745 1 THE CABINET DOORS BY THE PANTRY NEED TO BE ADJUSTED.
Cabinet doors above wall countertop
I first got drill and used the adjustment screws on the hinges
and I screwed them in and out on top and bottom till the door had
an even gap so the door would close properly

75745 2 THE REAR AIR PLENUM IS NOT STRAIGHT
rear ac plenum was not put on straight
i first removed ac plenum screws and loosened the main mouting
bolts to the ac and moved the ac o where it was straight and
tightened mounting bolts and put ac plenum back in place and made
sure that it looked straight

75745 3 BACK OF THE DINNETT VELCRO IS LOOSE
velcro on the back on dinette bench is loose
i first took pictures of the loose velcro then went and got the
air stapler and stapled the velcro on the back of the bench nd
made sure it was not loose anywhere

75745 4 LP DOOR ON THE DOOR SIDE RUBBS THE FRAME
door side lp door was hitting agenst the frame and not closing
properly

Claim : 75745

WO #	Job #	Description	JOB INFORMATION
------	-------	-------------	-----------------

i first noted where the door was hitting the frame and i took a deadblow hammer nd a block of wood and reshaped the door frame so that when closing the door it does not hit and it closes properly

Part No	Job#	Description	PARTS	Qty	Price	Total
116828	5	Vent - Screen - 14" x 14" - White		1.00	5.44	5.44

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	5	MISCELLANEOUS REPAIR		0.30	170.00	51.00
Z990	5	MISCELLANEOUS REPAIR		0.00	170.00	0.00
Z990	1	MISCELLANEOUS REPAIR		0.20	170.00	34.00
Z990	2	MISCELLANEOUS REPAIR		0.20	170.00	34.00
Z990	3	MISCELLANEOUS REPAIR		0.20	170.00	34.00
Z990	4	MISCELLANEOUS REPAIR		0.20	170.00	34.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	5	FREIGHT		1.00	24.72	24.72

Parts Total:	5.44
Labour Total:	187.00
Sublet Total:	0.00
Extras Total:	24.72

>>>> Claim Total: 217.16

Customer Signature: _____

Date: _____