

Pre-Authorization

Pre-Authorization number PA03798340 Reference no: 75745 Status: Approved Approved by stept VIN Retail sold on Approved date 1/21/2025
 Servicing Dealer Name Address

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction	
1194	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725					4YDFCGR28S2503116			
1	3100814A	Cabinet Door - Re	0.00	0.20	0.20		1	0.20	Complaint:THE CABINET DOORS BY THE PANTRY NEED TO BE ADJUSTED. Cause:Cabinet doors above wall countertop Correction:I first got drill and used the adjustment screws on the hinges and I screwed them in and out on top and bottom till the door had an even gap so the door would close properly	
2	4150215A	A/C - GE - Inside	0.00	0.20	0.20		1	0.30	Complaint:THE REAR AIR PLENUM IS NOT STRAIGHT Cause:rear ac plenum was not put on straight Correction:i first removed ac plenum screws and loosened the main mouting bolts to the ac and moved the ac o where it was straight and tightened mounting bolts and put ac plenum back in place and made sure that it looked straight	
3	3302214A	Dinette Cushions	0.00	0.20	0.20		1	0.20	Complaint:BACK OF THE DINNETT VELCRO IS LOOSE Cause:velcro on the back on dinette bench is loose Correction:i first took pictures of the loose velcro then went and got the air stapler and stapled the velcro on the back of the bench nd made sure it was not loose anywhere	
4	2302216A	Compartment Doc	0.00	0.20	0.20		1	0.20	Complaint:LP DOOR ON THE DOOR SIDE RUBBS THE FRAME Cause:door side lp door was hitting agenst the frame and not closing properly Correction:i first noted where the door was hitting the frame and i took a deadblow hammer nd a block of wood and reshaped the door frame so that when closing the door it does not hit and it closes properly	
5	2202608B	Plumbing Vent - F	0.00	0.20	0.30		1	0.30	Complaint:THE SCREEN IN THE BATHROOM HAS DIECOR ON IT Cause:Roof vent Screen has dicor on it Correction:I took pictures and filled out parts requests 1-17-25	
Pre-Authorization number PA03798340					1.10					

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return toKeystone RV Company