



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 75745  
Promised Date: 24 DEC 24

### CUSTOMER WORK ORDER

WO #: 75745

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag: BJ - SCREEN ORDERED. 1-22-25  
Author: BJW  
Location: 0129 CHECK STATUS WITH  
JG

Stock #: 11532  
Stock Desc: 2025 5W KEYSTONE  
COUGAR 316RLS  
Chassis #: 4YDFCGR28S2503116  
Serial #: 4YDFCGR28S2503116  
Mileage: 0  
Licence:

Invoice #:  
Date In: 30 DEC 24  
Promised: 31 DEC 24  
Date Sched:  
Completed: 29 JAN 25  
Warr. Date:

#### Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CAUSE: pdi new fifthwheel

CORRECTION: i first brought unit in and inspected roof and inspected all exterior seals and door comartments and found that the door side lp door needed to be adjusted then onece inside i made sure all cabinets were in proper condition nd found that the cabinet doors above the countertop and beside the pantry ere out of adjustment then i fould that the dinette bench had loose velcro on the back i then found that there was dicor on the roof vent screen in the bathroom then found that the rear ac plenum was not mounted straight i fixed all jobs added and i tested all appliances 120 and 12 volt and all lp appliances nd did lp drop test then winterized unit

#### Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JG	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JG	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JG	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JG	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

**Subtotal for Job #PDINFW: 0.00**

#### Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*

UNITS WITH WASHING MACHINE OR ICEMAKER  
WILL BE EXTRA

\*\*DE-WINTERIZATION IS NOT INCLUDED\*\*

NUMBER OF GALLONS USED \_\_\_\_\_

CAUSE: Winterize unit

CORRECTION: I first turned valves to winterize mode the hooked antifreeze to unit and turned on pump then ran antifreeze through all water lines and made sure all holding tanks were empty and the water heater was drained

#### Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JG	N/C

#### Parts

Customer #: 1000  
BASDEN'S AMERICAN RV,



W/O: 75745  
Promised Date: 31 DEC 24



Customer #: 1000  
BASDEN'S AMERICAN RV,



Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	3.00	N/C	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

**Subtotal for Job #WINTER: 0.00**

**Job #1 - Warranty**

COMPLAINT: THE CABINET DOORS BY THE PANTRY NEED TO BE ADJUSTED.

CAUSE: Cabinet doors above wall countertop

CORRECTION: I first got drill and used the adjustment screws on the hinges and I screwed them in and out on top and bottom till the door had an even gap so the door would close properly

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	34.00

**Subtotal for Job #1: 34.00**

**Job #2 - Warranty**

COMPLAINT: THE REAR AIR PLENUM IS NOT STRAIGHT

CAUSE: rear ac plenum was not put on straight

CORRECTION: i first removed ac plenum screws and loosened the main mouting bolts to the ac and moved the ac o where it was straight and tightened mounting bolts and put ac plenum back in place and made sure that it looked straight

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	34.00

**Subtotal for Job #2: 34.00**

**Job #3 - Warranty**

COMPLAINT: BACK OF THE DINNETT VELCRO IS LOOSE

CAUSE: velcro on the back on dinette bench is loose

CORRECTION: i first took pictures of the loose velcro then went and got the air stapler and stapled the velcro on the back of the bench nd made sure it was not loose anywhere

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	34.00

**Subtotal for Job #3: 34.00**

**Job #4 - Warranty**

COMPLAINT: LP DOOR ON THE DOOR SIDE RUBBS THE FRAME

CAUSE: door side lp door was hitting agenst the frame and not closing properly

CORRECTION: i first noted where the door was hitting the frame and i took a deadblow hammer nd a block of wood and reshaped the door frame so that when closing the door it does not hit and it closes properly

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	34.00



Subtotal for Job #4: 34.00

**Job #5 - Warranty**

COMPLAINT: THE SCREEN IN THE BATHROOM HAS DIECOR ON IT

CAUSE: Roof vent Screen has dicor on it

CORRECTION: I took pictures and filled out parts requests 1-17-25

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	51.00
Z990	MISCELLANEOUS REPAIR	JG	0.00

**Parts**

Part #	Description	Qty	Price	Total
116828	Vent - Screen - 14" x 14" - White -	1.00	5.44	5.44

**Other Services**

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	24.72	24.72

**Subtotal for Job #5: 81.16**

Parts Total: 5.44  
Labour Total: 187.00  
Sublet Total: 0.00  
Extras Total: 24.72  
**WORK ORDER TOTAL: 217.16**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 29 Jan 2025

Customer Signature : \_\_\_\_\_

W/O: 75745  
Promised Date: 31 DEC 24



Customer #: 1000  
BASDEN'S AMERICAN RV,

