

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2175961
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CXPB3SS048520
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	220 / 220A
OWNER INFORMATION		ITEM #	APTT241BHS
		DEALER RO #	75807
		CLAIM START DATE	01/18/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-99-01-00-001028	Operational Description Privacy Curtain Track - Interior/Soft Goods/Replace/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-01-18 14:56:14 :: CURTAIN TRACK IS LOOSE Curtain track was loose.. Installed multiple screws to secure track.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00
	Notes			

Labor

Line# 2	Operation Code 60-141-12-00-001592	Operational Description Tub Surround to Wall, each section - Plumbing/Shower, Tub Surround/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-01-18 14:58:04 :: SHOWER TUB MISSING SCREWS AND IS NOT SEALED Screws missing at shower base.. Installed screws to secure the wall liner to the base.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.05	Appr Labor Amt	\$8.50
	Notes We do not seal this area			

Labor

Line# 3	Operation Code 60-141-12-00-001592	Operational Description Tub Surround to Wall, each section - Plumbing/Shower, Tub Surround/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-01-18 14:59:12 :: ABOUT THE TUB IT IS MISSING TRIM TO HOLD THE WALL BACK Screw missing at top of shower liner... Sealed and installed screw to secure it to wall.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
	Notes			

Labor

Line# 4	Operation Code 30-103-24-00-001125	Operational Description Linoleum - Interior/Flooring/Repair/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-01-18 15:00:14 :: LINO NOT FLAT WHEN THE SLIDE IS OUT ALL THE WAY Manolium on endorsement slideout is wrinkled when opened.. Cut the manolium to size.			
Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$68.00

Serial#

Notes

What are you cutting?

area circled so it can lay flat

ok thank you

Labor

Line# 5

Operation Code

30-102-12-00-001096

Operational Description

Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-01-18 15:01:05 :: TRIM ABOVE THE SLIDE ROOM HAS COME LOOSE Trim above slideout was loose... Stapled trim into place.

Model#

Dlr Sub Hrs

0.10

Sub Labor Amt

\$17.00

Serial#

Appr Hrs

0.10

Appr Labor Amt

\$17.00

Notes

Submitted	Labor Amt	\$153.00	Approved	Labor Amt	\$144.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$153.00		Total	\$144.50

DEALER

SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.