

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75808
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11536 - 2025 APEX 242BARV 5ZT2CXNB0SS048414
VIN: 5ZT2CXNB0SS048414 HIN: SER#: 5ZT2CXNB0SS048414
Mileage: 0 Work Order Comp: 22 JAN 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 14 JAN 25 Inv #: 413376

WO # Job # Description JOB INFORMATION

75808 3 OUTDOOR ENTERTAINMENT DOOR MISSING INSERT TRIM ON FRONT
I FOUND THAT THE FRONT SIDE OF THE OUTSIDE ENTERTAINMENT WINDOW
/ DOOR WAS MISSING THE FRONT TRIM INSERT. I ORDERED A NEW INSERT
AND INSTALLED IT WHEN IT GOT HERE.

75808 9 BLACK TANK FLUSHER MISSING RUBBER
INSTALLED A NEW GROMMET IN THE BLACK TANK FLUSH PORT.

75808 1 BATHROOM DOOR HITTING FRAME
I ADJUSTED THE DOOR HINGES AND CHANGED THE MOUNTING POINTS FOR
THE HINGES. I HAD TO MOVE THE DOOR AWAY FROM THE 1/4 ROUND IN THE
DOOR JAM. NOW THE DOOR CLOSES AS IT SHOULD.

75808 2 WATER LEAKING BETWEEN AWNING RAIL
WHEN I PULLED THE CAMPER IN THE SHOP, I SEEN THAT WATER WAS
LEAKING FROM THE SEAM IN THE GUTTER. I SEALED THE GUTTER FROM THE
TOP AND BOTTOM TO PREVENT IT FROM LEAKING AGAIN.

75808 4 OUTDOOR ENTERTAINMENT DOOR SCREEN HITS SHOCK MOUNTS WILL NOT
CLOSE
I SHAVED DOWN THE SHOCK MOUNT ABOUT 1/8 INCH ON BOTH SIDES. NOW
THE SCREEN OPENS AND CLOSES AS IT SHOULD.

75808 5 WINDOW STYLE THAT HOLDS SUNSHADE STRING IS SPLIT IN BAR AREA
RIGHT SIDE
I REMOVED THE TRIM FROM THE SIDE OF THE WINDOW AND CUT A NEW 3/4

Claim : 75808

```

*****
WO #      Job #      Description      JOB INFORMATION
*****
X 3/4 INCH BOARD TO REPLACE THE ONE THAT WAS SPLIT. I REMOVED THE
BAD BOARD FROM THE TRIM AND INSTALLED THE NEW ONE. I PREDRILLED
THE HOLES TO KEEP IT FROM SPLITTING AGAIN ON INSTALL. I
REINSTALLED THE TRIM AND THEN TIGHTED THE BLIND AFTER
REINSTALLING THE STRINGS TO THE MOUNTED TRIM.

75808      6      BEDROOM SLIDING DOOR NOT MOVING
I ADJUSTED THE ROLLERS AT THE TOP THE THE DOOR SO THAT IT WAS NOT
SETTING ON THE LOWER KEEPER.

75808      7      GALLY TANK DRAIN WILL NOT HOOK UP TO SEWER
I FOUND THAT THE GALLEY TANK SEWER HOOKUP WAS MOUNTED HIGHER THEN
THE J-WRAP. I FOUND THAT I COULD FLIP OVER THE SEWER FITTING TO
CLEAR THE J-WRAP. SO I UNBOLTED THE FITTING FROM THE VALVE AND
FLIPPED THE SEWER PIPE OVER. NOW THE SEWER HOOKUP FITS WITHOUT
HAVING THE J-WRAP IN THE WAY.

75808      8      NEED TO RELOCATE THE LP HOOK UP TO OUTSIDE GRILL
I FOUND THAT THE LP HOSE FOR THE OUT SIDE GRILL WOULD NOT REACH
THE PORT UNDER THE UNIT. I WAS ABLE TO UNBOLT THE LP HOSE. I
STRAIGHTENED THE LP HOSE AND MOVED THE PORT BACK ON THE FRAME.
NOW THE GRILL IS IN LINE WITH THE PORT. I WAS ABLE TO TEST THE
GRILL AND PORT. IS WORKS AS IT SHOULD.

75808      10     THE ENTRY DOOR IS OUT OF ADJUSTMENT
I FOUND THAT THE MAIN DOOR WOULD NOT SHUT WITHOUT PUSHING VERY
HARD. I COULD NOT CLOSE THE DOOR AND GET IT TO LATCH FROM THE
INSIDE. I TRIED TO ADJUST THE DOOR IT SELF. I THEN ADJUSTED THE
STRICKER AND NOW THE DOOR WILL LATCH.

```

```

*****
Part No      Job#      Description      PARTS      Qty      Price      Total
*****
20-1376      3      Used For Doors/ Trim Molding And      1.00      1.98      1.98
10-1211      9      20183 3-PK 1" HOSE FILTERS      1.00      2.12      2.12

```

```

*****
Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total
*****
Z990      3      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      3      MISC LABOUR CODE (EXTERNAL)      0.10      170.00      17.00
Z990      9      MISC LABOUR CODE (EXTERNAL)      0.30      170.00      51.00
Z990      1      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00
Z990      2      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00
Z990      4      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00
Z990      5      MISC LABOUR CODE (EXTERNAL)      0.50      170.00      85.00
Z990      6      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00

```

Claim : 75808

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990        6  MISC LABOUR CODE (EXTERNAL)      0.00     170.00      0.00
Z990        7  MISC LABOUR CODE (EXTERNAL)      0.10     170.00     17.00
Z990        7  MISC LABOUR CODE (EXTERNAL)      0.20     170.00     34.00
Z990        8  MISC LABOUR CODE (EXTERNAL)      0.00     170.00      0.00
Z990        8  MISC LABOUR CODE (EXTERNAL)      0.50     170.00     85.00
Z990       10  MISC LABOUR CODE (EXTERNAL)      0.30     170.00     51.00

```

```

Parts Total:      4.10
Labour Total:    476.00
Sublet Total:      0.00
Extras Total:      0.00

```

```

>>>> Claim Total:    480.10

```

Customer Signature: _____

Date: _____