

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2185801
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CXPB6SS048592
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	220 / 220A
OWNER INFORMATION		ITEM #	APTT251RBK
		DEALER RO #	75861
		CLAIM START DATE	01/29/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor

Line# 1

Operation Code	20-46-24-00-000726	Operational Description
Complaint, Cause, Correction		Window Screen - Exterior/Windows/Repair/No Tread Code
		Original Note : bhoffman@americanrvcenter.com, 2025-01-29 15:41:43 :: EMERGENCY EXIT SCREEN IS TORN. emergency screen is torn took pics and took out and rescreened screen and reinstalled back in place.
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$34.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$34.00
Notes		

Labor

Line# 2

Operation Code	30-101-02-00-001076	Operational Description
Complaint, Cause, Correction		Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code
		Original Note : bhoffman@americanrvcenter.com, 2025-01-29 15:43:16 :: BATHROOM DOOR HITTING FRAME bathroom door hitting plastic at bottom plastic was bowed out at bottom,took off and cut bottom of plastic and reinstalled ,door dosent hit now.
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$34.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$34.00
Notes		

Labor

Line# 3

Operation Code	50-134-01-00-003645	Operational Description
Complaint, Cause, Correction		Outside Grill LP Hose with Valve - LP Gas/LP Gas System/Replace/No Tread Code
		Original Note : bhoffman@americanrvcenter.com, 2025-01-29 15:43:53 :: OUTSIDE GRILL IS MOUNTED BACKWARDS grill hose will not reach hookup tried to turn grill the other way but holes dont line up and it will not close,turned back the original way,need to get longer hose.
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.25	\$42.50
Serial#	Appr Hrs	Appr Labor Amt
	0.25	\$42.50
Notes		

Labor

Line# 4

Operation Code	20-58-01-00-000611	Operational Description
Complaint, Cause, Correction		Diamond Plate Aluminum - Exterior/Metal, Aluminum Siding/Replace/No Tread Code
		Original Note : bhoffman@americanrvcenter.com, 2025-01-29 15:45:09 :: SCREWS IN FRONT OF ROCK GUARD ARE COMING OUT screws came out of wood reinstalled screws in wood. Additional Note :

bhoffman@americanrvcenter.com, 2025-01-29 15:45:23 :: repair only

Model# Dlr Sub Hrs 0.10 Sub Labor Amt \$17.00

Serial# Appr Hrs 0.10 Appr Labor Amt \$17.00

Notes

Labor

Line# 5 Operation Code 10-3-01-20-000073 Operational Description Wheel Center Cap - Frame & Chassis/Wheels, Tires, Hubcaps/Replace/Wheels
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-01-29 15:45:58 :: LEFT REAR WHEEL CENTER CAP FELL OFF hub cover fell off took off wheel and reinstalled cap put wheel back on and retorqued.

Model# Dlr Sub Hrs 0.10 Sub Labor Amt \$17.00

Serial# Appr Hrs 0.05 Appr Labor Amt \$8.50

Notes

Labor

Line# 6 Operation Code 10-1-15-11-000059 Operational Description Brake Wiring - Frame & Chassis/Axles, Suspension/Repair or Replace/Electrical
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-01-29 15:46:39 :: RIGHT FRONT WHEEL HAS NOT BRAKES WIRE IS CUT IN THE AXLE right front brake dont work wire was broke off in axle, tried to fish out wire and no luck ,so pulled out wire on other side and ran across of axle and tied up and connected wires ,tested and it works fine.

Model# Dlr Sub Hrs 0.40 Sub Labor Amt \$68.00

Serial# Appr Hrs 0.30 Appr Labor Amt \$51.00

Notes

Labor

Line# 7 Operation Code 70-157-01-00-001824 Operational Description Door Hinge - Appliances/Refrigerator (Dometic)/Replace/No Tread Code
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-01-29 15:52:19 :: FREEZER BRACKITS ARE BROKEN INSIDE broken brackets for freezer shelf took pics and filled out sheet for parts.

Model# fcr08dcgta-kl Dlr Sub Hrs 0.25 Sub Labor Amt \$42.50

Serial# 10001629267102300002 Appr Hrs 0.10 Appr Labor Amt \$17.00

Notes

Labor

Line# 8 Operation Code 70-170-01-11-002040 Operational Description Furnace Sail Switch - Appliances/Furnace (Suburban)/Replace/Electrical
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-01-29 15:55:58 :: THE FURNACE WILL NOT COME ON furnance will not kick on. took off cushions and unscrewed board and took off cover and found switch was off, turned on and it works, reinstalled board and secured and installed cushions.

Model# na Dlr Sub Hrs 0.30 Sub Labor Amt \$51.00

Serial# na Appr Hrs 0.20 Appr Labor Amt \$34.00

Notes

Submitted	Labor Amt	\$306.00	Approved	Labor Amt	\$238.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$306.00		Total	\$238.00

DEALER _____ DATE _____

SIGNATURE
I certify that I have performed these repairs consistent with Forest

CUSTOMER _____ DATE _____

SIGNATURE
All repairs described have been inspected and are satisfactory.

