

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75867
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11541 - 2025 FREEDOM EXPRESS 247SE 5ZT2FEPB2SW030689
VIN: 5ZT2FEPB2SW030689 HIN: SER#: 5ZT2FEPB2SW030689
Mileage: 0 Work Order Comp: 07 FEB 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 28 JAN 25 Inv #: 413805

WO # Job # Description JOB INFORMATION

75867 3 THE SHOWER LINER IS NOT COMPLETELY SEALED ON ALL SIDES
Shower liner not sealed...
Used white silicone to seal right side of shower liner. Due to
the liners flex between the mount screws creating a bulge i had
to apply pressure while sealing and take down to pull liner
closer to wall so silicone could seal.
75867 1 STAIN ON CEILING NEXT TO SPEAKER
Pinkish spot on ceiling by speaker...
Attempted to clean it but wouldn't remove so I used white paint
marker to cover it.
75867 2 PANEL UNDER BED IS LOOSE
Loose panel under bed area...
Stapled panel into place.
75867 4 THE SEAM TAPE UNDER THE EMERGENCY EXIT WINDOW IN THE BEDROOM IS
FLAWED
Loose/Rippled seam tape..
Applied adhesive and stretched out to remove ripples and make
tightened.
75867 5 THERE IS A WATER STAIN ON THE CEILING ABOVE THE EMERGENCY EXIT IN
THE BEDROOM
Stain on wall by ceiling in bedroom.
Attempted to clean water mark but wouldn't remove so I covered

Claim : 75867

```

*****
WO #      Job #      Description      JOB INFORMATION
*****
          stain with white paint marker lightly. Applied all 2nd layer.
          Checked in roof and found no poor sealed areas.

75867      6      THE LATCH ON THE DRAWER NEAR THE BED IN THE BEDROOM DID NOT HAVE
          BOTH SIDES OF THE LATH ATTACHED PROPERLY FROM MANUFACTURING
          Drawer next to bed didn't have locking latch installed
          properly...
          Installed the locking mechanism with 2 screws.

75867      7      THE CABINET NEXT TO THE COUCH IS CRACKED AND FLAWED
          Cracked piece of trim and discolor on wall...
          Doctored the broken area and matched color of wax puddy to cover.

```

```

*****
Part No      Job#      Description      PARTS      Qty      Price      Total
*****
SIK432053      3      CLEAR SIKASIL PLUS      1.00      18.23      18.23

```

```

*****
Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total
*****
Z990      3      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      3      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00
Z990      1      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00
Z990      2      MISC LABOUR CODE (EXTERNAL)      0.10      170.00      17.00
Z990      4      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      4      MISC LABOUR CODE (EXTERNAL)      0.10      170.00      17.00
Z990      5      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      5      MISC LABOUR CODE (EXTERNAL)      0.10      170.00      17.00
Z990      6      MISC LABOUR CODE (EXTERNAL)      0.10      170.00      17.00
Z990      7      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00

```

```

Parts Total:      18.23
Labour Total:      170.00
Sublet Total:      0.00
Extras Total:      0.00

```

```

>>>> Claim Total:      188.23

```

Customer Signature: _____

Date: _____