



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75898
Promised Date:
08 FEB 25

CUSTOMER WORK ORDER

WO #: 75898

Customer: 43337 - WILL, CHRISTINA -
812-449-6158

Tag:

Author: BJW

Location: 0207 BH TO CLOSE

Stock #: 11462

Stock Desc: 2025 TT FOREST RIVER

CHEROKEE GREY WOLF 26DBH

Chassis #: 4X4TCKB21SK091814

Serial #: 4X4TCKB21SK091814

Mileage:

Licence:

Invoice #:

Date In: 03 FEB 25

Promised: 28 FEB 25

Date Sched:

Completed: 10 FEB 25

Warr. Date: 11 SEP 24

Job #1 - Warranty

COMPLAINT: ONE OF THE LICENSE PLATE HOLDER HOLES BROKE OFF.

CAUSE: License plate mount broke off.

CORRECTION: Took pictures of the damaged license plate taillight mount and put in po for a new taillight with license plate mount. Received the new taillight from the parts department. Pulled off the lens and unscrewed the light from the body. Disconnected the wires then wired in the new light and tested. Mounted the new light and trimmed with geosel. Put the broken taillight in the warranty department.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	34.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Parts

Part #	Description	Qty	Price	Total
438875	Light - Tail - Base & Lens Assembly	1.00	8.06	8.06

Subtotal for Job #1: 42.06

Job #2 - Warranty

COMPLAINT: THERE IS SOME OF THE SEALANT ON THE SLIDE ROOM THAT IS DRY AND BREAKING AWAY.

CAUSE: Geosel was very thin causing it to crack open

CORRECTION: Took pictures of the geosel cracked open on the slideroom. Got geosel from the parts department then applied to the cracked areas to seal up the voids.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	42.50

Parts

Part #	Description	Qty	Price	Total
10341	(CHEROKEE) SEALANT, GEOCEL 2300 MHRV	1.00	7.48	7.48

Subtotal for Job #2: 49.98

Job #3 - Internal

COMPLAINT: CUSTOMER CAME BY ON 02/03 TO PUT LICENSE PLATE ON IN STORAGE LOT. ONCE SHE GOT TO THE TRAILER, SHE CALLED US TO COME LOOK AT THE TRAILER WITH HER. THERE IS A RUG INSIDE THE MAIN ENTRY DOOR THAT IS SATURATED WITH WATER AND THERE ARE



Customer #: 43337
WILL, CHRISTINA

SEVERAL WATER STAINS IN THE FLOOR. IT LOOKS AS THOUGH THERE HAS BEEN A PRETTY SEVERE LEAK WHILE UNIT HAS BEEN IN STORAGE.

CAUSE: Slideroom roof leaking on the floor

CORRECTION: Opened the main entrance door and found the customers rug soaked with water. Put the rug in the dryer. Sprayed water along the entry door,slideroom then checked the inside for any water. On the end that has couch which is the front of the slideroom is where the water had been running off the slideroom roof onto the floor. Found water leaking about the middle of the slideroom with it closed. Ran the slideroom out for further inspection. Found a mound of leaves in the center of the slideroom roof. Cleaned out the mound of leaves and inspected the flap seal for any damages. No damage found to the flap seal. The flap seal is touching the slideroom roof as it should. Took pictures of the water stains on the slideroom roof ,slideroom exterior walls and the interior floor at the entry door. The dirt stains are from the leaves. Recommend a slide topper if continuous use around trees to prevent leaves building up on the slideroom roof. Closed up the slideroom and water tested again. After water testing the slideroom again checked for any further leaks, no more leaks occurred.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #3: 0.00

Parts Total: 15.54
Labour Total: 76.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 92.04

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Feb 2025

W/O: 75898
Promised Date: 28 FEB 25



Customer #: 43337
WILL, CHRISTINA

