

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75901
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11549 - 2025 CATALINA 283RKSLE 5ZT2CATB8SX034120
VIN: 5ZT2CATB8SX034120 HIN: SER#: 5ZT2CATB8SX034120
Mileage: 0 Work Order Comp: 14 FEB 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 04 FEB 25 Inv #: 413983

WO # Job # Description JOB INFORMATION

75901 5 THE TRIM AROUND THE BATHROOM DOOR IS OUT OF ALIGNMENT.
Bathroom plastic door frame up top has flaws...
Removed piece of plastic door frame and found uneven silicone and
pieces of trim pieces. Measured and put part request in for new
piece of frame. (NOTED to put white screw in the bottom of shower
liner)

75901 1 MAGNET PULLED OFF OF WALL IN FOR FRONT COMPARTMENT
Magnetic catch pulled from mounted area...
Filled in old mount holes and reinstalled, magnetic catch for
compartment door.

75901 2 CLOSET IN BEDROOM IS MISSING PANELS
Inside panel was missing from closet.
Closet panel measures 42 in tall and 22 3/4 in wide. Measured and
cut new panel. Removed clothing bar and mount from closet.
Installed panel with staples. Installed trim with staples. And
reinstalled clothing bar and mounts.

75901 3 JWRAP IS LOOSE
Loose JWrap where screw was pulled thru...
Reinstalled screw and added another to keep the 2 pieces secured
properly.

75901 4 THE DICOR BEAD ACROSS THE BACK OF THE RUBBER MEMBRANE IS VERY
THIN AND DOES NOT COVER EVERY THING THAT IT NEEDS TO.

Claim : 75901

```

*****
WO #      Job #      Description      JOB INFORMATION
*****
          Thin seal of dicor on back lip on roof...
          Used a full tube of white self leveling Dicor across the back lip
          area of roof.

75901      6      THE INTERIOR TRIM OVER THE TOP OF THE MAIN ENTRY DOOR IS NOT
          SECURED AND SEALED PROPERLY
          Trim above door not installed properly...
          Repositioned screws to stretch out piece of fabric covered trim
          and silicone the small remaining gap.

75901      7      THERE IS INSULATION STICKING OUT FROM AROUND THE INTAKE VENT FOR
          THE FURNACE.
          Insulation coming from blow vent...
          Removed vent and cut back piece of insulation. Reinstalled vent.

75901      8      THE ROOF MEMBRAINE UNDER THE SKYLIGHT ABOVE THE SHOWER WAS NOT
          TRIMMED PROPERLY AT THE MANUFACTURER
          Membrane wasn't trimmed properly around bathroom skylight...
          Removed inside skylight cover and trimmed back membrane flaps.
          Reinstalled skylight cover.

```

```

*****
Part No      Job#      Description      PARTS      Qty      Price      Total
*****
F100570470      5      DOOR JAMB 3-3/4"      1.00      7.03      7.03

```

```

*****
Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total
*****
Z990      5      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      5      MISC LABOUR CODE (EXTERNAL)      0.40      170.00      68.00
Z990      5      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      1      MISC LABOUR CODE (EXTERNAL)      0.10      170.00      17.00
Z990      2      MISC LABOUR CODE (EXTERNAL)      1.00      170.00      170.00
Z990      3      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00
Z990      4      MISC LABOUR CODE (EXTERNAL)      0.29      170.00      49.30
Z990      4      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      4      MISC LABOUR CODE (EXTERNAL)      0.40      170.00      68.00
Z990      6      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00
Z990      6      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      6      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      7      MISC LABOUR CODE (EXTERNAL)      0.50      170.00      85.00
Z990      7      MISC LABOUR CODE (EXTERNAL)      0.00      170.00      0.00
Z990      8      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00

```

```

*****
Excode      Job#      Description      EXTRAS      Qty      Price      Total
*****
FRT      5      UPS-DOOR JAMB      1.00      35.72      35.72

```

Claim : 75901

```
*****
Excode   Job#   Description      EXTRAS          Qty    Price    Total
*****
```

```

Parts Total:      7.03
Labour Total:    559.30
Sublet Total:      0.00
Extras Total:     35.72
```

```
>>>> Claim Total:    602.05
```

Customer Signature: _____

Date: _____