

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2194313
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2FEUB6SW030697
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	320 / 320
OWNER INFORMATION		ITEM #	FET288BHDS-320
		DEALER RO #	75918
		CLAIM START DATE	02/07/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 10-1-01-00-000047	Operational Description Axle Dust, Grease, or Bearing Cap - Frame & Chassis/Axles, Suspension/ Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-02-07 09:07:38 :: LF WHEEL CENTER CAP MISSING center cap is beat up need whole center cap it is bent up inside.filled out parts request.	
Model#	PART	Dlr Sub Hrs 0.20 Sub Labor Amt \$34.00
Serial#	MISSING	Appr Hrs 0.20 Appr Labor Amt \$34.00
	Notes	

Labor

Line# 2	Operation Code 10-1-01-00-000047	Operational Description Axle Dust, Grease, or Bearing Cap - Frame & Chassis/Axles, Suspension/ Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-02-07 09:10:40 :: LF WHEEL HUB IS OFF AND ROLLING IN CAP cap is off of hub took off rim and installed new cap,installed wheel back in place and retorqued.	
Model#	NA	Dlr Sub Hrs 0.20 Sub Labor Amt \$34.00
Serial#	NA	Appr Hrs 0.20 Appr Labor Amt \$34.00
	Notes	

Labor

Line# 3	Operation Code 30-102-01-00-001096	Operational Description Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-02-07 09:11:20 :: RF COMPARTMENT TRIM IS LOOSE trim loose in compartment secured trim back in place.	
Model#		Dlr Sub Hrs 0.20 Sub Labor Amt \$34.00
Serial#		Appr Hrs 0.20 Appr Labor Amt \$34.00
	Notes	

Labor

Line# 4	Operation Code 70-205-01-11-002313	Operational Description Attitude Mini Refrigerator - Appliances/Mini Refrigerator (Attitude)/Replace/ Electrical
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-02-07 09:11:53 :: OUTSIDE FRIDGE HAS DENTS IN DOOR outside ref has dents filed out sheet for new outside ref,it has dents in door.	

Model# AT16BF2

Dlr Sub Hrs 0.30

Sub Labor Amt \$51.00

Serial# NA

Appr Hrs 0.30

Appr Labor Amt \$51.00

Notes

R&R mini refridgerator DOOR

Submitted

Labor Amt	\$153.00
Parts & Freight	\$0.00
Total	\$153.00

Approved

Labor Amt	\$153.00
Parts & Freight	\$0.00
Total	\$153.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.