

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75942
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 54455 - MARY L. EBLEN
Address: 7208 HWY 60 E HENDERSON, KY

42420

Phone: 270-577-3404

Stock Number: 11287 - 2024 DELTA 262RB 7M5TD2922RC302222

VIN: 7M5TD2922RC302222 HIN: SER#: 7M5TD2922RC302222

Mileage: 0

Work Order Comp: 28 FEB 25

Auth. No:

Dealer #:

Warr. Date: 27 FEB 24

Work Order Date: 10 FEB 25

Inv #: 414614

WO # Job # Description JOB INFORMATION

75942	3	THE SCREWS IN THE SHOWER HEAD ARE PULLING LOOSE FOUND THAT SHOWER HEAD SCREWS PULLED OUT OF THE WALL. I INSTALLED WALL ANCHORS BEHIND SHOWER HEAD MOUNT. SEALED UP AROUND MOUNT.
75942	4	THERE IS A PLUG IN BY THE RECLINERS IS STARTING TO PULL LOOSE. I FOUND THAT THE USB PLUG ON THE WALL BAY THE RECLINER WAS PULLED OUT OF THE WALL. IT NEEDS TO BE REMOUNTED. I ADDED CLIPS TO THE PANELING TO KEEP THE SCREWS FROM PULLING OUT AND REINSTALLED THE USB PORT ON THE WALL.
75942	6	THERE IS A PIECE OF ANGLE IRON THAT IS LOOSE IN THE FRONT COMPARMENT. CAN IT BE RESECURED? FOUND THE ANGLE IN THE COMPARTMENT. NEEDS TO BE REINSTALLED. I REINSTALLED THE ANGLE ON THE WALL AND PUT THE BUNGEE BACK IN PLACE TO HOLD THE COVER PANEL.
75942	8	THE SLIDING BATHROOM DOOR HAS A BROKEN CATCH ON THE BOTTOM THE BATHROOM DOOR NEEDS TO HAVE THE LOWER HOLD-BACK REMOUNTED AND GLUE THE CORNER TRIM. THEN REINSTALL THE HOLD-BACK. I REMOVED THE DOOR HOLD-BACK AND FIXED THE TRIM. THEN I REINSTALLED THE DOOR HOLD-BACK.
75942	9	THE FRAMEWORK ABOVE THE BATHROOM SLIDING DOOR IS LOOSE AND COMING DOWN REMOVED THE LIGHT ON THE CEILING SO THAT I COULD CHECK AN SEE IF

Claim : 75942

 WO # Job # Description JOB INFORMATION

 THERE WAS ANYTHING OVER THE TRACK TO SCREW TO. I FOUND THAT THERE
 IS A 1x4 OVER THE TRACK AND I WAS ABLE TO SCREW THE TRIM BACK UP
 TO THE CEILING. I ADDED 5 MORE SCREWS TO THE TRIM TO HOLD IT IN
 PLACE.

75942 10 THE WOOD PANELING THAT IS TO THE LEFT OF THE KITCHEN SINK IS
 LOOSE AND NEEDS TO BE REATTACHED.
 SIDE OF CABINET NEEDS REPAIRED
 I REMOVED THE BAD PART UNDER THE CABINET AND REPAIRED IT. I ADDED
 MORE SCREWS AND FIXED THE SIDE SO THAT IT WAS NOT LOOSE.

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 8 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 9 MISC LABOUR CODE (EXTERNAL) 0.50 185.00 92.50
 Z990 10 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00

Parts Total: 0.00
 Labour Total: 240.50
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 240.50

Customer Signature: _____

Date: _____