

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2222898
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZTCFLS07TP432864
USA		CHASSIS VIN	1FDWE3FN9SDD30100
		MILEAGE	371
Labor rate:	\$185.00	SITE/WAREHOUSE	210 / 210
OWNER INFORMATION		ITEM #	FLC27QBF35
		DEALER RO #	75948
		CLAIM START DATE	03/07/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	40-196-24-11-001297	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-03-07 11:51:03 :: CAP USP PORTS DONT WORK Found that there isn't a charge coming from the usb ports due to a loose wire not connected properly Check cap USB Restored proper connection to the usb ports by putting the wire into the connector and now the usb ports work as originally intended Found that the front cap lights need to be on to power the bunk USB to work.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50
	Notes			
	1) ok nw			

Labor

Line# 2	Operation Code	Operational Description		
	30-98-01-00-000997	Bed Hinge - Interior/Beds, Mattress/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-03-07 11:51:43 :: BED COMPARTMENT DOOR HINGES ARNT SCREWED IN Found that the bedroom compartment hinges weren't bolted down properly and was causing it to not be able to open properly due the screws not being long enough Installed longer screws into the hinges and now the compartment door is operating properly			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	40-106-01-00-001258	Heating Pad - Holding Tank - Electrical/12 Volt Exterior/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-03-07 11:52:21 :: GREY TANK HEAT PAD FELL OFF grey tank pad fell off took pics and filled out sheet for new pad. I HAD TO SCRAP ALL OF THE GLUE OFF THE TANK AND CLEAN THE BOTTOM OF THE TANK SO THAT THE NEW HEATING PAD WOULD STAY ON. AFTER CLEANING THE TANK, TO TREATED THE TANK WITH 3M PROMOTER. I PUT THE NEW TANK HEATER ON AND TESTED. EVERYTHING IS WORKING AS IT SHOULD.			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$92.50
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$92.50
	Notes			

Labor

Line# 4	Operation Code	Operational Description		
	20-69-02-17-000708	Compartment Door Lock or Slam Latch - Exterior/Compartment Doors/Adjust/		

Latch

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-03-07 11:52:49 :: TIGHTEN THUMB LATCH ON LP DOOR.
Tighten thumb latches on LP door. I tightened the lp door thumb latches and found that they need to remain a little loose or they will not turn

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
Notes				

Labor

Line# 5

Operation Code

40-196-01-11-001275

Operational Description

Single Pancake Light Lens - Electrical/12 Volt Interior/Replace/Electrical

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-03-07 11:53:20 :: MISSING LENS CAP ON CEILING LIGHT
FOUND THAT THE LENS CAP ON 1 LIGHT WAS MISSING ORDERED A LIGHT AND REPLACED IT WHEN IT SHOWED UP.

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50
Notes				

Submitted

Labor Amt	\$240.50
Parts & Freight	\$0.00
Total	\$240.50

Approved

Labor Amt	\$240.50
Parts & Freight	\$0.00
Total	\$240.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.