

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2202143
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CXNBXRS047006
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	220 / 220A
OWNER INFORMATION		ITEM #	APTT243FKS
		DEALER RO #	75957
		CLAIM START DATE	02/14/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description			
	30-102-12-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2025-02-14 16:37:39 :: There is a piece of trim on the front side of the bedroom slide-out that does not align properly with the adjoining trim. This misalignment is most noticeable when walking from the living area to the bedroom. Additionally, the piece of trim by the bedside is uneven. I found that the roller was not level with the floor, so I removed the roller along with the board it was mounted to, which consisted of two stacked boards. I then removed one of the boards, reinstalled the remaining board, roller, and the piece of trim.				
Model#		Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50
Serial#		Appr Hrs	0.30	Appr Labor Amt	\$55.50
Notes					

Submitted	Labor Amt	\$55.50	Approved	Labor Amt	\$55.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$55.50		Total	\$55.50

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____

DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.