

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2219159
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TRPU15KB022639
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	080 / 080
OWNER INFORMATION		ITEM #	RPT190-80
RUTH HORN		DEALER RO #	75964
6534 WATERFORD PLACE		CLAIM START DATE	03/04/2025
Owensboro, KY 42303		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	08/14/2019	WARRANTY EXPIRATION DATE	08/14/2020

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	RC-003-22--003240	19V356, 2019-235 - WIRE FROM THE REFRIGERATOR HAS INCORRECT CIRCUIT - Recall/Electrical/Rewire/		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-03-04 16:39:59 :: 19V356, 2019-238 - WIRE FROM THE REFRIGERATOR HAS WRONG CIRCLE Recall on the fridge wire going to the converter and needed to be switched to a different wire I first removed cover and removed converter then identified the wires needing to be switched and removed and switched the wires as call for in the recall and tapped everything up and put the converter back in the hole and put the cover back into place			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$92.50
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$92.50
	Notes	authorized 1.00		

Labor

Line# 2	Operation Code	Operational Description		
	SB-467-13--003293	51-1058 - MEDICINE CABINET MAY FALL - Technical Service Bulletin/Medicine Cabinet/Relocate/		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-03-04 16:40:53 :: 51-1058 - MEDICINE CABINET MAY FALL Recall for medical cabinet I did steps on recall and I found that the medicine cabinet was mounted to the metal frame with a magnetic stick then made sure the cabinet was straight in the wall and did not need to be moved			
Model#	Dlr Sub Hrs	1.00	Sub Labor Amt	\$185.00
Serial#	Appr Hrs	1.00	Appr Labor Amt	\$185.00
	Notes	authorized 1.00		

Labor

Line# 3	Operation Code	Operational Description		
	SB-510-01-00-003449	51-1086 - P-TRAP SWIVEL FITTING - Technical Service Bulletin/Plumbing/ Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-03-04 16:41:34 :: 51-1086 - P-TRAP SWIVEL FITTING P trap recall I first removed the ptrap and swivel in the kitchen and replaced then when removing the one in the bathroom I could not get the new one to line back up properly i then tried the old one and I could still not get it to go back on properly I then had to get an extension and made the tube going to the p trap was long enough I then put the new swivel and ptrap on the bathroom sink			

