



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75964
Promised Date:
28 FEB 25

CUSTOMER WORK ORDER

WO #: 75964

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0305 BH TO CLOSE

Stock #: 11446A
Stock Desc: 2019 TT FOREST RIVER
RPOD RP190
Chassis #: 4X4TRPU15KB022639
Serial #: 4X4TRPU15KB022639
Mileage: 0
Licence:

Invoice #:
Date In: 13 FEB 25
Promised: 28 FEB 25
Date Sched:
Completed: 28 FEB 25
Warr. Date:

Job #PDIUCTT - Internal

COMPLAINT: PDI USED CERTIFIED TRAVEL TRAILER 11446A R POD

CAUSE: Pdi used travel trailer

CORRECTION: I brought unit in and found the 7 way needed replaced lights in the living room needed replaced, front jacks need replaced, lp cover, water heater rod, and all 4 corners need vinyl replaced and silicone cleaned i then did everything on sheet and winterized unit then did all 4 recalls

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Parts

Part #	Description	Qty	Price	Total
19-1811	A10-3025ED 30A 25' TWISTLOCK	1.00	N/C	N/C
9816	ALUMINUM ANODE ROD	1.00	N/C	N/C
40564	40564 PW 20# SINGLE LP COVER	1.00	N/C	N/C
03-0255	SMOKE ALARM	1.00	N/C	N/C
DF-SA135-BK	DF-SA135-BK BLACK SHOWER WAND	1.00	N/C	N/C
479579	LED - Mushroom Light - Ultra Bright	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDIUCTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: I first disconnected city water and put into winterize mode and hooked to antifreeze then turned on pump and made sure water heater was off then ran antifreeze through all water lines and made sure all holding tanks including water heater were empty

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 1000
BASDEN'S AMERICAN RV,



Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Internal

COMPLAINT: BOTH FRONT SCISSOR JACKS

CAUSE: Replace front jacks

CORRECTION: I removed bent jacks in the front and replaced with new and made sure the worked properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Parts

Part #	Description	Qty	Price	Total
285326	24IN SCISSOR JACK KIT WITH CRANK HAN	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: REPLACE THE INSERT AND PEAL THE EXTRA SILICONE OFF AND FIX

CAUSE: replace vnyle strips all 4 cornors and clean off all silicone off fron end and off the vnyle strips

CORRECTION: i first removed the vnyle strips and cleaned off all excess silicone off and replaced with new vnyle strips on both sides then cleaned out all uncured silicone on the fron of unit and tapped off and ut new silicone to seal the unit

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Parts

Part #	Description	Qty	Price	Total
E569	E569 HEAVY DUTY INSERT TRIM MOLDING	1.00	N/C	N/C
219088	SILICONE II BLACK	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: REPALCE THE 7 WAY

CAUSE: replace 7 way cord

CORRECTION: i first removed the wire conectors to the 7 way and wired in the new 7 way with heat shrink conectors then too the wire mounts into the frame and removed 7 way and ut the new 7 way into place and de sure it worked properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

W/O: 75964
Promised Date: 28 FEB 25



Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 75964
 Promised Date: 28 FEB 25



Customer #: 1000
 BASDEN'S AMERICAN RV,



Parts				
Part #	Description	Qty	Price	Total
19430	10' MOLDED 7-WAY CORD	1.00	N/C	N/C
Subtotal for Job #3:				0.00

Job #19V356 - Warranty

COMPLAINT: 19V356, 2019-238 - WIRE FROM THE REFRIGERATOR HAS WRONG CIRCLE

CAUSE: Recall on the fridge wire going to the converter and needed to be switched to a different wire

CORRECTION: I first removed cover and removed converter then identified the wires needing to be switched and removed and switched the wires as call for in the recall and tapped everything up and put the converter back in the hole and put the cover back into place

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	92.50
Subtotal for Job #19V356:			92.50

Job #51-1058 - Warranty

COMPLAINT: 51-1058 - MEDICINE CABINET MAY FALL

CAUSE: Recall for medical cabinet

CORRECTION: I did steps on recall and I found that the medicine cabinet was mounted to the metal frame with a magnetic stick then made sure the cabinet was straight in the wall and did not need to be moved

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	185.00
Subtotal for Job #51-1058:			185.00

Job #51-1086 - Warranty

COMPLAINT: 51-1086 - P-TRAP SWIVEL FITTING

CAUSE: P trap recall

CORRECTION: I first removed the ptrap and swivel in the kitchen and replaced then when removing the one in the bathroom I could not get the new one to line back up properly i then tried the old one and I could still not get it to go back on properly I then had to get an extension and made the tube going to the p trap was long enough I then put the new swivel and ptrap on the bathroom sink

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JG	120.25
Z990	MISC LABOUR CODE (EXTERNAL)	JG	24.05
Z990	MISC LABOUR CODE (EXTERNAL)	JG	40.70
Z990	MISC LABOUR CODE (EXTERNAL)	JG	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JG	0.00

Parts				
Part #	Description	Qty	Price	Total
100485	P-TRAP - KEYSTONE	2.00	2.84	5.68
111200	Fitting - ABS - Adapter - 1 1/2" - S	1.00	2.40	2.40
89-8002	COUPLING 1 1/2" H X H	2.00	1.10	2.20
Subtotal for Job #51-1086:				195.28

Job #20V763 - Warranty

COMPLAINT: 20V763, 2020-606 - PLUMBING CONCERNS



CAUSE: Recall on termination valves

CORRECTION: I first saw there was not a strap and nothing broke si I cut metal strap and put on both grey and black tank termination valves as the recall stated

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	55.50
Subtotal for Job #20V763:			55.50

Job #4 - Internal

COMPLAINT: THE ENTRY DOOR THRESHOLD IS NOT SECURED PROPERLY AND IT MOVES UP AND DOWN WHEN STEPPING ON THE ENTRY STEPS.

CAUSE: Rotten floor causing the entry step to be unstable

CORRECTION: Pulled the camper into the service bay. Plugged in the shore power and turned on the interior lights to see the floor better. Cut the linoleum on both sides of the entry door and peeled back. Got with Chad on the floor damage. Set a fan in front of the entry door to dry out the wet wood. Let the floor dry out overnight. Cut out the rotten wood and let the floor dry out more. Drilled holes thru the supporting wood beam then bolted it to the frame. Steps still needed more support, welded the steps to the frame. Cut a new piece of wood to fit in the entry way. Put liquid nail down and stapled the new wood panel to the floor. Let the liquid nail dry overnight and used wood filler to fill and voids. Sanded the floor, applied linoleum glue to the flooring then used the roller to press out bubbles. Trimmed the entry way with trim and threshold plate.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Subtotal for Job #4:			0.00

Parts Total: 10.28
 Labour Total: 518.00
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 528.28

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 Mar 2025

W/O: 75964
Promised Date: 28 FEB 25



Customer #: 1000
BASDEN'S AMERICAN RV,

