

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

CLAIM STATUS Authorized
CLAIM 2230816
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2CARB3SU044286
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 103 / 103
ITEM # CAT261BH-8
DEALER RO # 76022
CLAIM START DATE 03/14/2025
CLAIM END DATE 01/01/1900

Labor rate: \$185.00

OWNER INFORMATION

SUSANNA H ROBERTS
 317 SOUTH 3RD STREET
 Rockport, IN 47635
 USA

Retail Date of Purchase 03/15/2025

WARRANTY EXPIRATION DATE 03/15/2026

Claim Line Details

Labor

Line# 1	Operation Code 70-147-24-00-001769	Operational Description TV Coax Cable - Appliances/Television/Repair/No Tread Code
----------------	--	--

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-03-14 16:10:13 :: THERE IS NO SIGNAL TO THE TELEVISION IN THE BEDROOM Coaxial cable for the antenna was attached to the wrong input of the tv booster During the final pdi was testing the tv signal but had no signal to the bedroom. Unscrewed the booster from the wall to checked signal. Chased the coaxial cable to find the antenna cable was in the wrong location. Put the cables in the correct spots on the booster and now have signal.

Model#	Dir Sub Hrs	0.80	Sub Labor Amt	\$148.00
Serial#	Appr Hrs	0.60	Appr Labor Amt	\$111.00

Notes

EXCESSIVE AMOUNT REQUESTED. CHANGED TO SIMILAR REPAIR TIME

Submitted	Labor Amt	\$148.00
	Parts & Freight	\$0.00
	Total	\$148.00

Approved	Labor Amt	\$111.00
	Parts & Freight	\$0.00
	Total	\$111.00

DEALER _____ DATE _____
 SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE

All repairs described have been inspected and are satisfactory.