



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76024
Promised Date:
28 FEB 25



CUSTOMER WORK ORDER

WO #: 76024

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0516 CHECK STATUS WITH
BB

Stock #: 11553
Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 231MKS
Chassis #: 5ZT2CAMB3SU045431
Serial #: 5ZT2CAMB3SU045431
Mileage:
Licence:

Invoice #:
Date In: 26 FEB 25
Promised: 28 FEB 25
Date Sched:
Completed: 08 MAY 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*76426 on 08 APR 25
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CAUSE: New unit pdi

CORRECTION: Pulled camper in. Hooked up test battery. Purged and filled the lp tanks. Added company decals and safety labels. Checked the coupler and tongue jack and jack light. Checked the steps. Checked the exterior lights. Checked the brakes on all 4 wheels and checked the brake away on all for wheels. Set the tire pressures to 70 psi on all the tires. Torqued all the lugnuts down to 110 ft lbs. Checked all exterior seals on the windows, doors, lights, compartments, and roof. Tested the rest of the jacks. Tested the outside speakers. Tested the awning and awning lights. Checked the awning for any rips, tears, or blemishes. Tested the outside outlets. Tested the city water port and the fresh water port. Inspected the exterior door and screen door. Tested the slide room mechanism. Tested all interior lights. Tested all outlets and usb ports. Checked all doors and cabinet doors. Checked all panels and hinges. Tested the lp detector and the smoke alarm. Tested the refrigerator and the microwave. Removed all the packing tape from the fridge and microwave. Checked the fuse box and tested the breakers. Tested the reclining seats. Tested the floats for the fresh, gray, and black tanks. Ran all of the antifreeze out of the lines and checked for leaks. Tested the ac for 10 mins. Tested the furnace for 10 mins. Tested the stove. Tested the range hood. Tested the water heater. Recorded all the serial and model numbers for the camper. Also found stains on the reclining couch and a mark on the fridge. Tested the antenna. Performed the lp drop test. Completed the new unit pdi.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	AAS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	AAS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	AAS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	AAS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	AAS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	AAS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	AAS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	AAS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Customer #: 1000
BASDEN'S AMERICAN RV,





Job #WINTER - Internal

Transferred to BAS*76426 on 08 APR 25
 Estimate amount was 0.00
 WINTERIZE UNIT AND DRAIN HOLDING TANKS.
 INCLUDES 2 GALLONS OF ANTI-FREEZE
 UNITS WITH WASHING MACHINE OR ICEMAKER
 WILL BE EXTRA
 DE-WINTERIZATION IS NOT INCLUDED
 NUMBER OF GALLONS USED _____

Labor				
Code	Description		Mechanic	Total
Z990	WINTERIZE UNIT		AAS	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #1 - Internal

COMPLAINT: THE 7WAY MALE PLUG ON THE TRAILER DOES NOT CONNECT TO THE FEMALE RECIEVER PROPERLY.

CAUSE: Found that the male connector for the 7way cable was damaged prior to arrival

CORRECTION: Disconnected the old 7way cable and wired up and installed the new cable on the new unit.
 All lights and power are working with the new cable.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		AAS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		AAS	N/C
Parts				
Part #	Description	Qty	Price	Total
19430	10' MOLDED 7-WAY CORD	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Warranty

COMPLAINT: MAIN COUCH THERE IS A STAIN ON THE SEAT COUSION WHEN LOOKING AT IT ON THE LEFT

CAUSE: Found on the left seat cushion is a cluster of white stains found upon delivery and was listed in the delivery notes

CORRECTION: Applied some cleaner to a rag and scrubbed the seat cushion till the stains went away and let it sit for 10 mins to make sure the stains didn't reappear. The stains didn't reappear after letting it sit for 10 mins.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		AAS	18.50
Subtotal for Job #2:				18.50

Job #3 - Warranty

SMALL DENT ON OFF DOOR SIDE REAR BY REAR WINDOW

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		AAS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		BB	508.75
Z990	MISC LABOUR CODE (EXTERNAL)		BB	231.25





Parts				
Part #	Description	Qty	Price	Total
F100134895	12" SILVER METAL X 167"	1.00	32.32	32.32
Other Services				
Code	Description	Qty	Price	Total
FRT	FREIGHT & CRATE - METAL	1.00	338.08	338.08
Subtotal for Job #3:				1,110.40

Parts Total: 32.32
Labour Total: 758.50
Sublet Total: 0.00
Extras Total: 338.08
WORK ORDER TOTAL: 1,128.90

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 08 May 2025

Customer Signature : _____

