

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 76051
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 46875 - CHUBBY CHOW FACTORY LLC
Address: PO BOX 3641 EVANSVILLE, IN

47735

Phone: 812-455-2400

Stock Number: 11524 - 2026 FREELANDER 27QB 1FDWE3FN3SDD32716

VIN: 1FDWE3FN3SDD32716 HIN: SER#: 1FDWE3FN3SDD32716

Mileage: 342

Work Order Comp: 28 FEB 25

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 26 FEB 25

Inv #: 414644

WO # Job # Description JOB INFORMATION

76051 1 PASSENGER REAR SIDE COMPARTMENT NEEDS ADJUSTED
Outside rear pass. compartment needs adjusted...
Adjusted compartment door so it wouldn't rub door frame.

76051 2 INTERIOR OVERHEAD CABINET DOOR OVER DINETTE PULLED FROM HINGES
Overhead compartment screws in hinge stripped...
Installed thicker screws due to old screws stripped out wood.

76051 3 BATHROOM DOOR NEEDS ADJUSTMENT
Bathroom door rubbing striker plate...
Adjusted striker plate so latch/door wouldn't rub and latch.

76051 4 THERE IS WATER LEAKING FROM THE FILTER SIDE OF THE PUMP WHEN
PLUMBING IS PRESSURIZED
WATER LEAK AT PUMP WHEN TRYING TO FILL TANK. Leaks on both sides
of water pump and the inline water filter when attempting to fill
fresh water tank...
I FOUND THAT THE FRESH WATER FILL WAS HOOKED UP TO THE COLD WATER
LINES GOING TO THE SHOWER AND THE COLD WATER LINE FROM THE SHOWER
WAS HOOKED UP TO THE FRESH WATER TANK INLET. WE FOUND UNDER THE
STOVE WAS WERE THE WATER LINES GOT CROSSED. WE SWAPPED THE WATER
LINES AND NOW THE FRESH WATER TANK FILL WORKS AND THE COLD WATER
GOES TO ALL FIXTURES. After opening all the removable panels to
locate all valves and line me and Greg air pressure tested and
tracked down all the ins and outs lines and final located the
Fresh Water fill port was connected to the outlet side of pump

Claim : 76051

 WO # Job # Description JOB INFORMATION

and not connected to the Fresh tank. After trial and error and tracking down all the lines we found that at the low point valve drain area located under the stovetop that 2 lines were installed in each other correct spots. Cut the crimp bands on both lines and swapped the lines and tested with air pressure. When reconnecting water inlet to fresh tank and putting inlet water filter back into place i found the housing of filter was crack, received new filter housing from parts and installed. Filled fresh tank and tested all lines and all worked properly. Put all panels and parts back into place.

76051 5 THE TOILET WAS NOT HOOKED TO PLUMBING. WILL NEED TO PULL TOILET. ALSO FOUND WATER LINE TO TOILET TO BE CAPPED OFF. Toilet not flushing, water line was capped off and connected to toilet... Had to remove toilet to gain access to water line to remove cap and connected to toilet.

76051 6 THE PLATFORM THAT THE MATTRESS LAYS ON CAME OFF OF THE HINGES. When propping open the underbelly compartment to work on freshtank and pump the screws pulled from hinges and out of cover board... Installed larger diameter screws.

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	1	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		1.00	185.00	185.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		1.00	185.00	185.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.15	185.00	27.75
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.05	185.00	9.25

Parts Total: 0.00
 Labour Total: 629.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 629.00

Customer Signature: _____

Date: _____