



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76051

CUSTOMER WORK ORDER

WO #: 76051

Customer: 46875 - CHUBBY CHOW
FACTORY LLC - 812-455-2400

Tag:

Author: BJW

Location: 0305 CHECK PREAUTH

Stock #: 11524

Stock Desc: 2026 C COACHMEN
FREELANDER 27QB

Chassis #: 1FDWE3FN3SDD32716

Serial #: 1FDWE3FN3SDD32716

Mileage: 342

Licence:

Invoice #:

Date In: 26 FEB 25

Promised:

Date Sched:

Completed: 28 FEB 25

Warr. Date:

Job #PDINMHC - Internal

COMPLAINT: PDI - NEW MOTORHOME "C"

CAUSE: Pdi...

CORRECTION: Drove unit around the lot and filled LP and moved unit into bay then checked Transmission, Shifted Gears, Climated Control. Checked Lugs, Tire Pressure, All exterior lights, and Stabilizer Jacks. Checked Trans Fluid, Power Steering fluid, Coolant, Brake Fluid and Oil. Checked Roof and installed Vent Covers (2). Checked Generator Oil and started her up. Checked all Cap Seals and compartments, and doors on exterior. Attempted to fill fresh tank and had to address a water line issue that was installed incorrect... found and corrected Water issue and filled tank. Preformed a LP DropTest. Checked appliances. Checked all recepticals and USB ports. Checked all lights, compartment, drawers and doors on interior. Checked all windows and blinds. Checked TV and internet wifi and radio. Ran sink and toilet to drain the Fresh tank and activate Grey and Black floats in tanks. Double checked all water connections for leaks. Installed stickers in correct places. Took all my manufacturer labels and filled out all my PDI paperwork.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
86-8275	255-313 THREADED IN-LINE FILTER	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	16.00	N/C	N/C

Subtotal for Job #PDINMHC: 0.00

Job #FPDINMH - Internal

COMPLAINT: FINAL PDI ON NEW MOTORHOME CLASS C

CAUSE: Final pdi...

CORRECTION: Went thru checksheet and double checked all areas.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,



Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #FPDINMH: 0.00

Job #MAXX - Internal

COMPLAINT: ROOF VENT COVER - INSTALLED EACH 2 VENTS

CAUSE: Install vent covers on 2 vent on roof...

CORRECTION: Installed brackets on on vents and bolted the vent cover on brackets.

Labor				
Code	Description		Mechanic	Total
Z990	INSTALL MAXX AIR VENT		JRK	N/C

Parts				
Part #	Description	Qty	Price	Total
22-0257	40443 BLK CAMCO VENT COVER	2.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C

Subtotal for Job #MAXX: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit...

CORRECTION: Winterized unit and filled out checksheet.

Labor				
Code	Description		Mechanic	Total
Z990	WINTERIZE UNIT		JRK	N/C

Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: PASSENGER REAR SIDE COMPARTMENT NEEDS ADJUSTED

CAUSE: Outside rear pass. compartment needs adjusted...

CORRECTION: Adjusted compartment door so it wouldn't rub door frame.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JRK	37.00

W/O: 76051



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,



Subtotal for Job #1: 37.00

Job #2 - Warranty

COMPLAINT: INTERIOR OVERHEAD CABINET DOOR OVER DINETTE PULLED FROM HINGES

CAUSE: Overhead compartment screws in hinge stripped...

CORRECTION: Installed thicker screws due to old screws stripped out wood.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	55.50
Subtotal for Job #2:			55.50

Job #3 - Warranty

COMPLAINT: BATHROOM DOOR NEEDS ADJUSTMENT

CAUSE: Bathroom door rubbing striker plate...

CORRECTION: Adjusted striker plate so latch/door wouldn't rub and latch.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	37.00
Subtotal for Job #3:			37.00

Job #4 - Warranty

COMPLAINT: THERE IS WATER LEAKING FROM THE FILTER SIDE OF THE PUMP WHEN PLUMBING IS PRESSURIZED

CAUSE: WATER LEAK AT PUMP WHEN TRYING TO FILL TANK.

Leaks on both sides of water pump and the inline water filter when attempting to fill fresh water tank...

CORRECTION: I FOUND THAT THE FRESH WATER FILL WAS HOOKED UP TO THE COLD WATER LINES GOING TO THE SHOWER AND THE COLD WATER LINE FROM THE SHOWER WAS HOOKED UP TO THE FRESH WATER TANK INLET. WE FOUND UNDER THE STOVE WAS WERE THE WATER LINES GOT CROSSED. WE SWAPPED THE WATER LINES AND NOW THE FRESH WATER TANK FILL WORKS AND THE COLD WATER GOES TO ALL FIXTURES.

After opening all the removable panels to locate all valves and line me and Greg air pressure tested and tracked down all the ins and outs lines and final located the Fresh Water fill port was connected to the outlet side of pump and not connected to the Fresh tank. After trial and error and tracking down all the lines we found that at the low point valve drain area located under the stovetop that 2 lines were installed in each other correct spots. Cut the crimp bands on both lines and swapped the lines and tested with air pressure. When reconnecting water inlet to fresh tank and putting inlet water filter back into place i found the housing of filter was crack, received new filter housing from parts and installed. Filled fresh tank and tested all lines and all worked properly. Put all panels and parts back into place.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	185.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	185.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Subtotal for Job #4:			370.00

Job #5 - Warranty

COMPLAINT: THE TOILET WAS NOT HOOKED TO PLUMBING. WILL NEED TO PULL TOILET. ALSO FOUND WATER LINE TO TOILET TO BE CAPPED OFF.

CAUSE: Toilet not flushing, water line was capped off and connected to toilet...

Customer #: 46875
CHUBBY CHOW FACTORY
LLC,

CORRECTION: Had to remove toilet to gain access to water line to remove cap and connected to toilet.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	92.50

Subtotal for Job #5: 92.50

Job #6 - Warranty

COMPLAINT: THE PLATFORM THAT THE MATTRESS LAYS ON CAME OFF OF THE HINGES.

CAUSE: When propping open the underbelly compartment to work on freshtank and pump the screws pulled from hinges and out of cover board...

CORRECTION: Installed larger diameter screws.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	27.75
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	9.25

Subtotal for Job #6: 37.00

Parts Total: 0.00
Labour Total: 629.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 629.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 Mar 2025

W/O: 76051



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,

