

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 76072
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 46875 - CHUBBY CHOW FACTORY LLC
Address: PO BOX 3641 EVANSVILLE, IN

47735

Phone: 812-455-2400

Stock Number: 11525 - 2026 FREELANDER 27QB 1FDWE3FN7SDD30130

VIN: 1FDWE3FN7SDD30130 HIN: SER#: 1FDWE3FN7SDD30130

Mileage: 0 Work Order Comp: 07 JUL 25

Auth. No: Dealer #:

Warr. Date: 07 MAY 25 Work Order Date: 01 MAR 25 Inv #: 419636

WO # Job # Description JOB INFORMATION

76072 2 HEATING PAD FELL OFF
Heating pad fell off
I removed fallen heating pad and cleaned tank for new one to be
wired in and stuck onto the tank then made sure it was working
properly

76072 7 BATHROOM SHOWER WALL CRACKED UNDER THE FAUCET
Bathroom shower wall cracked
Removed shower wall faucet from wall then removed wall and put
new wall in place and put the faucet back into place

76072 11 WATER HEATER CONTROL PAD IS BROKEN

76072 12 MINI BLIND BENT

76072 1 LP LEAK
Lp leak after doing lp drop test
First I tried to spray down all outdoor lines and conections then
did regulator and grill quick port then tried to do an lp drop
test at a different location and still had a leak i then spraied
line going into the range top inside and also spraied the line
going into furnace then spraied line going into water heater and
found that there was a leak in then tightened the line and did lp
drop test and found that that was the leak and there was no
longer any leaks

Claim : 76072

```

*****
WO #      Job #      Description      JOB INFORMATION
*****
76072      3      SCREEN DOOR NEEDS ADJUSTED
              Screen entry door needs adjusted
              The screen door handle was loose and needed to be tightened and
              the catch plate needed to be pushed down to make the door catch
              the door latch

76072      4      BATHROOM SHOWER LEAKING AT THE SHOWER MISER
              Shower miser leaks
              I took access pannel off wall behind shower miser then found that
              the conections were never properly sealed so I then had to remove
              and put seal tape around all of the fitting that didn't have any
              then made sure there was no more leaks

76072      5      BATHROOM TOWEL HOLDER PULLED OUT OF WALL
              Bathroom towel holder fel out of wall
              I first removed the rest of holder and put screw wall anchors in
              holes and screwed back to the wall and made sure it was secure

76072      8      WATER HEATER IS MOUNTED WRONG
              Water heater is mounted crooked. There is a gap. On the inside
              left and the hinge side of the door is being pushed out. This is
              being caused by the water lines on the back of the water heater.
              The lines are too long and they are pushing the back side of the
              water heater to the rear of the unit.
              I unhooked the water lines at the back of the water heater. This
              allowed me to straighten the water heater and mount it properly.
              After remounting the water heater from the outside, I was able to
              address the the water line problem. I was able to shorten the hot
              water line and make it work. Is the cold water line, I had to
              move the valve to the vertical position. There was not enough
              room on the water line to keep it in the horizontal position.
              After moving the valve, I was able to get the rest of the cold
              water line to fit as it should.

76072      9      WHITE INSERT ON REAR WALL POPING OUT OF TRACK
              Insert trim shrank and pulled out.
              I stretched the insert trim back over to the corner and screwed
              it down in the corner.

76072      10     BACK UP CAMPER GROMIT PULLED OUT OF WALL
              The camera grommet would not fit in the wall.
              I found that the wall was too thick for the camera wire grommet.
              The hole was the right size. I was able to cut the inside lip off
              of the wire grommet and push it into the wall. After I got it to
              fit, I sealed up the inside of the hole with silicone and the
              silicone will also keep the grommet from coming out.

```

Claim : 76072

 WO # Job # Description JOB INFORMATION

76072 13 THE ROOF AND THE BACK WALL ARE NOT EVEN AND NEEDS TO BE TRIMMED DOWN
 The back wall extends vertically over the roof base. This is lifting the roofing up. The back wall needs to be trimmed down, and the roof material needs to be pulled back and down. Need to remove the trim on the top of the back wall. Trim the roof and pull the material down to lay flat on the roof. Then put the trim back on the back wall and seal it up.

76072 14 DEAD BOLT WONT NOT LOCK
 Adjust door to get deadbolt to lock
 The door was not straight from top to bottom. I adjusted the door. Now the door is even with the door frame. The deadbolt would still not latch. I found that the deadbolt was barely hitting the door frame. If you pushed on the door very hard, the deadbolt would lock. I tapered and rounded over the corner of the deadbolt. Only around 1/16" on the corner. Now the deadbolt locks. I found that something was rubbing. After looking, I seen that the striker pin needed to be spaced out a bit. I added 1 washer behind the pin and now the door opens, closes, and locks as it should.

76072 15 BLACK TANK SUPPORT PIPE IS BROKEN
 Black tank pipe strap is missing the bolt that holds it together. I found a carriage bolt that fits the strap. I found a nylon lock nut and washer. I installed the bolt, washer, and lock nut in the pipe strap clamp.

76072 17 SHOWER PAN SUPPORT IS LOOSE
 Shower pan fetch very soft. I checked it from the bottom side and found that the support was not touching the shower base. When I was removing the shower wall to replace it, I pulled up the shower pan and found that the support leg did not touch the floor with the platform in the right place. I removed the leg and cut a new one to hold up the platform. I moved the platform into the right position and screwed it down. Now, the platform is secured and will not move out of place. I reinstalled the shower pan. Now the unit is ready for the new shower wall.

 Part No Job# Description PARTS Qty Price Total

F100689025	2	HEATER, HOLDING TANK 50 GAL MAX,		1.00	69.71	69.71
F100584251	7	SURROUND, SHOWER SENECA BENT WALL		1.00	159.68	159.68
2.01.1.0207	11	Wired Controller (for RV Water He		1.00	50.59	50.59

Claim : 76072

```

*****
Part No      Job#  Description          PARTS          Qty      Price      Total
*****
890033       12  BLIND, 20X24 WHITE W/VAL + HLD BR  0.00      10.87       0.00
F100128180   12  BLIND, 20X26 WHITE W/VAL + HLD BR  1.00       3.94       3.94

```

```

*****
Lab Code     Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990         2  MISC LABOUR CODE (EXTERNAL)          0.38     185.00     70.30
Z990         2  MISC LABOUR CODE (EXTERNAL)          0.12     185.00     22.20
Z990         7  MISC LABOUR CODE (EXTERNAL)          0.19     185.00     35.15
Z990         7  MISC LABOUR CODE (EXTERNAL)          0.31     185.00     57.35
Z990         7  MISC LABOUR CODE (EXTERNAL)          0.00     185.00       0.00
Z990         7  MISC LABOUR CODE (EXTERNAL)          1.00     185.00    185.00
Z990         7  MISC LABOUR CODE (EXTERNAL)          1.00     185.00    185.00
Z990         7  MISC LABOUR CODE (EXTERNAL)          0.00     185.00       0.00
Z990        11  MISC LABOUR CODE (EXTERNAL)          0.30     185.00     55.50
Z990        12  MISC LABOUR CODE (EXTERNAL)          0.10     185.00     18.50
Z990        12  MISC LABOUR CODE (EXTERNAL)          0.10     185.00     18.50
Z990         1  MISC LABOUR CODE (EXTERNAL)          0.66     185.00    122.10
Z990         1  MISC LABOUR CODE (EXTERNAL)          0.04     185.00      7.40
Z990         3  MISC LABOUR CODE (EXTERNAL)          0.20     185.00     37.00
Z990         4  MISC LABOUR CODE (EXTERNAL)          0.00     185.00       0.00
Z990         4  MISC LABOUR CODE (EXTERNAL)          0.30     185.00     55.50
Z990         4  MISC LABOUR CODE (EXTERNAL)          0.00     185.00       0.00
Z990         5  MISC LABOUR CODE (EXTERNAL)          0.20     185.00     37.00
Z990         8  MISC LABOUR CODE (EXTERNAL)          0.30     185.00     55.50
Z990         8  MISC LABOUR CODE (EXTERNAL)          0.90     185.00    166.50
Z990         9  MISC LABOUR CODE (EXTERNAL)          0.30     185.00     55.50
Z990        10  MISC LABOUR CODE (EXTERNAL)          0.20     185.00     37.00
Z990        13  MISC LABOUR CODE (EXTERNAL)          0.00     185.00       0.00
Z990        13  MISC LABOUR CODE (EXTERNAL)          2.00     185.00    370.00
Z990        14  MISC LABOUR CODE (EXTERNAL)          0.20     185.00     37.00
Z990        15  MISC LABOUR CODE (EXTERNAL)          0.20     185.00     37.00
Z990        17  MISC LABOUR CODE (EXTERNAL)          0.00     185.00       0.00
Z990        17  MISC LABOUR CODE (EXTERNAL)          1.00     185.00    185.00

```

```

*****
Excode       Job#  Description          EXTRAS          Qty      Price      Total
*****
FRT          2  UPS-HEATER                      1.00     15.54     15.54
FRT          7  UPS FREIGHT & CRATE - SURROUND    1.00    130.15    130.15
FRT         11  FREIGHT                        1.00     15.58     15.58
FRT         12  FREIGHT                        1.00     15.58     15.58

```

Parts Total: 283.92
 Labour Total: 1,850.00
 Sublet Total: 0.00
 Extras Total: 176.85

>>>> Claim Total: 2,310.77

Customer Signature: _____

Date: _____