



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76074
Promised Date:
20 MAR 25

CUSTOMER WORK ORDER

WO #: 76074

Customer: 46875 - CHUBBY CHOW
FACTORY LLC - 812-455-2400

Tag: 2603R

Author: BJW

Location: 0731 CHECK STATUS WITH
ZMS

Stock #: 11527

Stock Desc: 2026 C COACHMEN

FREELANDER 27QB

Chassis #: 1FDWE3FN7SDD32380

Serial #: 1FDWE3FN7SDD32380

Mileage: 0

Licence:

Invoice #:

Date In: 01 MAR 25

Promised: 29 MAR 25

Date Sched:

Completed: 30 JUL 25

Warr. Date: 25 APR 25

Job #PDINMHC - Internal

Transferred to BAS*76359 on 31 MAR 25

Estimate amount was 0.00

PDI - NEW MOTORHOME "C"

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINMHC: 0.00

Job #FPDINMH - Internal

Transferred to BAS*76359 on 31 MAR 25

Estimate amount was 0.00

FINAL PDI ON NEW MOTORHOME CLASS C

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #FPDINMH: 0.00

Job #MAXX - Internal

ROOF VENT COVER - INSTALLED EACH 2 VENTS

Labor

Code	Description	Mechanic	Total
Z990	INSTALL MAXX AIR VENT	ZMS	N/C
Z990	INSTALL MAXX AIR VENT	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
22-0257	40443 BLK CAMCO VENT COVER	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C

Customer #: 46875
CHUBBY CHOW FACTORY
LLC,



Subtotal for Job #MAXX: 0.00

Job #WINTER - Internal

Transferred to BAS*76359 on 31 MAR 25

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	ZMS	N/C
Z990	WINTERIZE UNIT	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: BLACK TANK SENSOR'S WONT READ

CAUSE: Tank sensors are not reading.

CORRECTION: Tested voltage going into diode pack. The voltage reads 8.5. Removed monitor panel on the inside of the coach and tested voltage. 14.5 going into to monitor panel. Tested voltage on the fresh, grey and black tank wires. All are reading 8.5 volts DC. Tested all sensors using a jumper wire and a diode. All sensors are working. Replaced scotch lock connectors with wire caps for the the positive and negative wires.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	31.45
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	61.05

Subtotal for Job #1: 92.50

Job #2 - Warranty

COMPLAINT: GREY TANK SENSORS WONT READ

CAUSE: Tank sensors are not reading.

CORRECTION: Tested voltage going out of monitor panel. Removed scotch lock connectors and replaced with wire caps. Filled tank to test sensors. Drain tanks.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	92.50

Subtotal for Job #2: 92.50

Job #3 - Warranty

COMPLAINT: SHOWER BLEND VLAVE IS LEAKING

CAUSE: The shower blend valve is leaking internally.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00





Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	74.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
F100224120	FAUCET - SOP: SHOWER DIVERTER W/ ICO	1.00	13.75	13.75

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-FAUCET	1.00	15.53	15.53

Subtotal for Job #3: 103.28

Job #4 - Warranty

COMPLAINT: THE REAR ROOF TRIM NEEDS DICOR

CAUSE: There is a gap on the top of the roof trim.

CORRECTION: Received dicor from parts. Got a lift and removed Santander dirt from trim and roof.
 Applied dicor as needed.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.00

Parts

Part #	Description	Qty	Price	Total
13-1287	NON SELF LEVELING DICOR	1.00	7.72	7.72

Subtotal for Job #4: 44.72

Job #5 - Warranty

TANK HEATER FELL OFF GREY TANK

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	40.70
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	51.80

Parts

Part #	Description	Qty	Price	Total
F100689025	HEATER, HOLDING TANK 50 GAL MAX, RV	1.00	73.20	73.20

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT - F.R. PARTS	1.00	130.15	130.15

Subtotal for Job #5: 295.85

Job #6 - Warranty

COMPLAINT: SCRTCHES ON STILE ABOVE CABINET DOOR

CAUSE: The Stile is scratched above cabinets.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	370.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	12.95
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	46.25



Z990 MISC LABOUR CODE (EXTERNAL) ZMS 33.30

Parts

Part #	Description	Qty	Price	Total
F100403620	STILE, FAWN MAPLE 18MM, 2"X8" RADIUS	8.00	1.00	8.00

Subtotal for Job #6: 470.50

Job #7 - Warranty

COMPLAINT: CABINET DOOR HAS A CHUNK MISSING

CAUSE: Cabinet door has a chunk missing.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
F100583620	DOOR, SLB MDF 14 X 32 FAWN MAPLE 202	1.00	19.38	19.38
F100583620	DOOR, SLB MDF 14 X 32 FAWN MAPLE 202	1.00	19.38	19.38

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-CABINET DOORS	1.00	15.51	15.51

Subtotal for Job #7: 109.77

Job #8 - Warranty

COMPLAINT: DOORS ABOVE STOVE ARE RUBBING

CAUSE: Doors are rubbing above the stove.

CORRECTION: Took a hammer and moved the hinges away from each other.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	18.50

Subtotal for Job #8: 18.50

Job #9 - Warranty

COMPLAINT: DENT ON WALL PANEL IN BEDROOM

CAUSE: Wall panel in the bedroom has a dent at the top. We will need to remove the window, valance, blind and surrounding trim to remove and replace the panel.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	323.75
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
F100583623	LAUAN, 1/8" X 48" X 96" VERT GRADE	1.00	57.50	57.50

W/O: 76074
Promised Date: 29 MAR 25



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,



Subtotal for Job #9: 381.25

Job #10 - Warranty

COMPLAINT: BEDROOM COAX HAS AN OPEN CIRCUIT

CAUSE: There is no signal going to the bedroom cable hook up. I installed a coax tester and found an open circuit.

CORRECTION: Removed booster from wall removed power wire. Removed coax that was next to bedroom coax. Cut off both cable ends and installed new ones. Tester says the cable is good. Installed booster. Installed cover plate in bedroom.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	129.50
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Subtotal for Job #10: 129.50

Job #11 - Internal

COMPLAINT: SILICONE ON TV

CAUSE: There is silicone on the TV.

CORRECTION: Removed with mineral spirits and a rag.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #11: 0.00

Job #12 - Warranty

COMPLAINT: CURTAIN HANGER NEEDS ADJUSTED

CAUSE: Curtain hanger is pushing up against the wall.

CORRECTION: Repositioned awafrom the wall. Filled holes with putty.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Subtotal for Job #12: 37.00

Job #13 - Warranty

COMPLAINT: ENTRY DOOR DEAD BOLT WONT LOCK WHEN DOOR IS SHUT

CAUSE: The deadbolt functions but it won't go into the latch. The deadbolt is centered. Need to be advised by warranty for repair.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.00

Subtotal for Job #13: 37.00

W/O: 76074
Promised Date: 29 MAR 25



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,



W/O: 76074
Promised Date: 29 MAR 25

Parts Total:	198.93
Labour Total:	1,452.25
Sublet Total:	0.00
Extras Total:	161.19
WORK ORDER TOTAL:	1,812.37

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 30 Jul 2025



Customer Work Order

Customer #: 46875
CHUBBY CHOW FACTORY
LLC,

