



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76080
Promised Date:
20 MAR 25

CUSTOMER WORK ORDER

WO #: 76080

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0313 CHECK PREAUTH

Stock #: 11554
Stock Desc: 2025 TT COACHMEN
REMOTE 17R
Chassis #: 5ZT2RMFC7SL018762
Serial #: 5ZT2RMFC7SL018762
Mileage: 0
Licence:

Invoice #:
Date In: 03 MAR 25
Promised: 29 MAR 25
Date Sched:
Completed: 13 MAR 25
Warr. Date:



Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER - 3 HR PDI

CAUSE: Pdi new unit

CORRECTION: Did everything on sheet and made sure all 120 and 12 volt appliances worked properly then did lp drop test and winterized

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: I first disconnected city water and put into winterize mode and hooked to antifreeze then turned on pump and made sure water heater was off then ran antifreeze through all water lines and made sure all holding tanks including water heater were empty

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JG	N/C

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



Customer #: 1000
BASDEN'S AMERICAN RV,



24181 -50 RV ANTI-FREEZE GALLON 2.00 N/C N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: THE KITCHEN BLIND HOLD DOWN ARE MISSING

CAUSE: Missing blind holder

CORRECTION: I mounted blind holder into place

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	9.25

Parts

Part #	Description	Qty	Price	Total
A301	A301 MINI BLIND HOLD-DOWN HOOK	1.00	3.05	3.05

Subtotal for Job #1: 12.30

Parts Total: 3.05

Labour Total: 9.25

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 12.30

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 13 Mar 2025

W/O: 76080
Promised Date: 29 MAR 25



Customer #: 1000
BASDEN'S AMERICAN RV,

