

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 76096
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 46932 - SCOTT D. TRAMMEL
Address: 903 W PLUM ST HARRISBURG, IL

62946

Phone: 618-926-6257

Stock Number: 11422 - 2025 COUGAR HALF-TON 25FKD 4YDTCGM28SV500287

VIN: 4YDTCGM28SV500287 HIN:

SER#: 4YDTCGM28SV500287

Mileage: 0

Work Order Comp: 06 MAR 25

Auth. No:

Dealer #: 1194

Warr. Date: 13 SEP 24

Work Order Date: 04 MAR 25

Inv #: 414708

WO # Job # Description JOB INFORMATION

76096 2 CHECK SHELF IN FRONT STORAGE BAY CAME LOOSE
Shelf fell apart and pulled out the staples
Inspected the shelf for why it fell apart. There was no
structural support at the edge of the shelf causing it to fall
down. Cut some trim to fit under the shelf to hold it up. Put the
trim style tape over another trim board then screwed it to the
wall to hold the shelf then tested the strength of the shelf.

76096 3 CHECK TRIM ON DOORWAY BETWEEN BATHROOM AND BEDROOM COMING LOOSE
Factory double sided tape wasn't sticking to the wood
Pulled down the overhead trim and checked the stickiness of the
double sided tape. Tape wasn't sticking at all. Added 2 more
strips of double sided tape and put tape primer on the tape and
pushed the trim back in place.

76096 1 RIVET THAT HOLDS LOWER J WRAP ON FRONT SLIDE IS NOT ATTACHED TO
BRACKET
Screw to short
Inspected the j wrap and the bracket that holds them together.
Found the screw was to short, screw didn't have enough threads to
catch the bracket. Unscrewed the screw and put in a longer screw
to hold the j wrap to the bracket.

76096 4 SPOT ON THE FRONT CAP HAS GLUE OR SOMETHING
Possible roof glue on the front cap
Soaked the affected area with goo gone and used a plastic razor

Claim : 76096

 WO # Job # Description JOB INFORMATION

blade then scraped off the glue. Wiped the area several more
 times with goo gone for a clean finish.

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	2	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.10	170.00	17.00
Z990	1	MISCELLANEOUS REPAIR		0.50	170.00	85.00
Z990	4	MISCELLANEOUS REPAIR		0.40	185.00	74.00

Parts Total: 0.00
 Labour Total: 210.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 210.00

Customer Signature: _____

Date: _____