

e-Authorization

4/5/20
11:05:28

3-Authorization number PA03833445 Reference no: 76241 Status: Approved Approved by gainw Approved date 4/4/2025
rving Name Address VIN Retail sold on

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDF42938LF810367	9/18/2019
----	----------------------	---	-------------------	-----------

lu Root e operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
------------------------------	-------------	--------	-----------	-------------------	-----------------	-----	---------------	--------------------------------

1	7138142A	Safety Advisory 2	0.00	0.70	0.70	1	0.70	Complaint:REPLACE ANTENNA RECALL Cause:Received the replacement antenna form the parts department. Went on the roof and unscrewed the recall antenna. Disconnected the the coaxial cables. Connected one of the coaxial cable but waiting on the other antenna. Mounted the new antenna but not dicor yet. Correction:Received the replacement antenna form the parts department. Went on the roof and unscrewed the recall antenna. Disconnected the the coaxial cables. Connected one of the coaxial cable but waiting on the other antenna. Mounted the new antenna but not dicor yet.
---	----------	-------------------	------	------	------	---	------	---

3-Authorization number PA03833445 0.70

r paper claims only use one pre-authorization number per warranty claim for
ple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the