

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2270654
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CANB6SN301263
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	300 / 300
OWNER INFORMATION		ITEM #	CAT243RBSLE-300
		DEALER RO #	76257
		CLAIM START DATE	04/21/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description
	30-100-24-00-001056	Backsplash - Interior/Cabinetry/Repair/No Tread Code
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2025-04-21 12:42:30 :: THE BACKSPLASH IS COMING OFF AND NEEDS TO BE REINSTALLED Back splash loose Added spray adhesive now is stuck on wall	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.10	\$18.50
Serial#	Appr Hrs	Appr Labor Amt
	0.10	\$18.50
	Notes	
	AUTHORIZED AS REQUESTED	

Labor

Line# 2	Operation Code	Operational Description
	30-99-01-00-001012	Mini-Blind - Interior/Soft Goods/Replace/No Tread Code
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2025-04-21 12:46:02 :: THE BLIND HAS A BEND IN IT AND NEEDS TO BE REPLACED Blind off track need to replace the blind	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$37.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$37.00
	Notes	

Labor

Line# 3	Operation Code	Operational Description
	10-11-24-00-000205	Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Repair/No Tread Code
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2025-04-21 12:48:03 :: SLIDE SEAL TOO LONG AND NEEDS TO BE TRIMMED DOWN AND RE-ATTACHED ON THE TOP REAR CORNER. trimmed down the seal and reinstalled	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$37.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$37.00
	Notes	

Labor

Line# 4	Operation Code	Operational Description
	70-150-01-00-001737	Microwave Glass Plate or Ring - Appliances/Microwave/Replace/No Tread Code
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2025-04-21 12:49:07 :: TRIM RING FOR MICROWAVE IS BROKEN FOUND THE RING IS BROKEN AND NEEDS REPLACED	
Model# NA	Dlr Sub Hrs	Sub Labor Amt
	0.00	\$0.00
Serial# NA	Appr Hrs	Appr Labor Amt
	0.00	\$0.00

Notes

Labor

Line# 5 Operation Code Operational Description
30-103-24-00-001125 Linoleum - Interior/Flooring/Repair/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2025-04-21 12:49:42 :: The lino is up in front of the fire place
Bubble in front of fireplace Took off vent cover took a pry bar to it lifted flooring put glue down no bubble
showing
Model# Dlr Sub Hrs 0.10 Sub Labor Amt \$18.50
Serial# Appr Hrs 0.10 Appr Labor Amt \$18.50
Notes
AUTHORIZED AS REQUESTED

Submitted	Labor Amt	\$111.00	Approved	Labor Amt	\$111.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$111.00		Total	\$111.00

DEALER DATE
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER DATE
SIGNATURE

All repairs described have been inspected and are satisfactory.