

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 76289
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 53382 - MARK A. MARTIN
Address: 12256 S 525 W CYNTHIANA, IN

47612

Phone: 812-499-1786

Stock Number: 11484 - 2025 CATALINA 303RKDSLE 5ZT2CAVB4SX033236

VIN: 5ZT2CAVB4SX033236 HIN:

SER#: 5ZT2CAVB4SX033236

Mileage: 0

Work Order Comp: 16 JUN 25

Auth. No:

Dealer #:

Warr. Date: 27 FEB 25

Work Order Date: 24 MAR 25

Inv #: 418748

WO # Job # Description JOB INFORMATION

76289 4 UNDER KITCHEN SINK THERES A PIPE RUNNING THROUGH WOOD THAT CAN SEE LIGHT AROUND IT NEEDS FOAM INSULATION
Pulled unit into shop. Opened slide room. There is a vent pipe that runs under the sink and goes through the wall. There is a cut out in the wall for the vent and it is missing insulation. There is also light coming in from the outside. Spoke with warranty. Warranty instructed me to removed the outside vent. Remove the clear geocell. And apply black silicone to block out the light. Warranty also approved removing the sink to gain access to wall. After inspection, the plumbing for the sink is all hard pipe and is glued together. The sink needs to be dropped to remove it and this will cause more work due to the plumbing being in the way. Spoke with Warranty advisor and he approved removing the back wall and trim to gain access to the wall and pipe to add insulation.
Removed trim and grate. Took a pry bar and popped the wall panel loose. Applied spray foam and let dry. Applied more foam the fill the rest of the gaps and let dry. Removed excess foam and cleaned up mess. Installed wall panel, trim and grate. Removed outside vent cover. Cut out clear geocell. Applied black silicone. Installed vent cover and sealed with black silicone. Cleaned up area.

76289 5 BEDROOM SLIDE BY CLOSET CAN SEE LIGHT THROUGH BOTTOM CORNER OF SLIDE
Light gap on the slide room corner.

Claim : 76289

WO # Job # Description JOB INFORMATION

Warranty advisor suggested a foam block from a previous repair. Cut foam and applied 3m adhesive primer. Pushed a small piece in between the bottom and side wiper seals. Light gap is much smaller than before. A small amount of light is normal. There aren't any signs of water coming in the slide room.

76289 7 HOLE IN SCREEN DOOR AT TOP
 Replace top screen.
 Removed door. Removed spline and screen. Cut a new piece of screen. Placed on a work bench. Installed new screen material. Installed door.

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.90	185.00	166.50
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.25	185.00	46.25
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.25	185.00	46.25
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00

Parts Total: 0.00
 Labour Total: 407.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 407.00

Customer Signature: _____

Date: _____