

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA Labor rate: \$185.00 OWNER INFORMATION ARTHUR SANUEL GURDO JR 1425 WILLIS AVE Enfield, IL 62835 USA Retail Date of Purchase 04/30/2024	CLAIM STATUS Authorized CLAIM 2246795 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CKGC2PY028887 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 095 / 095A ITEM # CKTR18TO-95 DEALER RO # 76310 CLAIM START DATE 03/29/2025 CLAIM END DATE 01/01/1900 WARRANTY EXPIRATION DATE 04/30/2025
--	--

Claim Line Details

Labor

Line# 1	Operation Code 70-155-01-11-001810	Operational Description EverChill Mini Refrigerator - Appliances/Mini Refrigerator (EverChill)/Replace/ Electrical
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-03-29 12:49:50 :: OUTSIDE MINI FRIDGE NOT WORKING Pulled unit up to shop. Opened slide room. Removed mounting bolts hold fridge in place. Removed the fridge from the unit. Plugged the fridge in and turned the t stat all the way up. Came in the next day and the fridge is not cold at all. The compressor is running and is hot. Need approval for replacement fridge.	
	Model# RV-170BK	Dlr Sub Hrs 0.50 Sub Labor Amt \$92.50
	Serial# 2205000699	Appr Hrs 0.50 Appr Labor Amt \$92.50
	Notes All Dealers must submit the following when requesting authorization for this repair: 1. A picture of the data tag with the model & serial numbers. 2. A picture of the cord cut off the back of the product. 3. A detailed description of the problem. "Inop," "defective," or "don't work" are not acceptable descriptions.	

Labor

Line# 2	Operation Code 20-43-01-00-000589	Operational Description Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-03-29 12:52:48 :: CHECK DECALS STARTING TO PEEL OFF DOOR SIDE WOLF PUP DECAL FOUND DECALS PEALING AND NEEDS REPLACED REINSTALL NEW DECALS	
	Model#	Dlr Sub Hrs 0.60 Sub Labor Amt \$111.00
	Serial#	Appr Hrs 0.50 Appr Labor Amt \$92.50
	Notes replace	

Labor

Line# 3	Operation Code 30-102-01-00-001096	Operational Description Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-03-29 12:54:51 :: STAPLES COMING OUT OF MOLDING OF BED Trim on bed is loose and has a staple hanging out. Removed staples. Secured with Brad rails. Filled holes with putty.	

Model#

Dlr Sub Hrs 0.20

Sub Labor Amt \$37.00

Serial#

Appr Hrs 0.20

Appr Labor Amt \$37.00

Notes

Submitted	Labor Amt	\$240.50
	Parts & Freight	\$0.00
	Total	\$240.50

Approved	Labor Amt	\$222.00
	Parts & Freight	\$0.00
	Total	\$222.00

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.