

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 76338
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 46875 - CHUBBY CHOW FACTORY LLC
Address: PO BOX 3641 EVANSVILLE, IN

47735

Phone: 812-455-2400

Stock Number: 2602R - 2026 FREELANDER 27QB 1FDWE3FN3SDD32716

VIN: 1FDWE3FN3SDD32716 HIN: SER#: 1FDWE3FN3SDD32716

Mileage: 0 Work Order Comp: 31 JUL 25

Auth. No: Dealer #:

Warr. Date: Work Order Date: 28 MAR 25 Inv #: 420517

WO #	Job #	Description	JOB INFORMATION
76338	4	HEATING PAD FELL OFF FOUND THAT THE HEATING PAD FELL OFF AND DRAGGED ON THE GROUND AND NEEDS REPLACED DONE REMOVE THE WIRING AND CLEAN THE TANK AND REINSTALL A NEW HEATING PAD DONE PREBILLED	
76338	5	SEWER FLUSH IS LEAKING REALLY BAD Black tank flusher was never hooked up to tank I found that the pipe going to the black tank was about 1 inch to short to use a 90 degree elbow to hook up the pipe to the tank. I was able to use 2 fittings together to get the pipe to reach. I installed a 90 degree threaded elbow in the tank and then I clamped a straight pex fitting to the pipe. I was then able to thread the 2 new fittings together. Tested tank flusher and it works as it should with no leaks.	
76338	1	LP DOES NOT READ I found that the wires were crossed on the molex plug going to the LP tank from the monitor panel. I unscrewed the refrigerator. I removed. The monitor panels from the wall. I twisted the refrigerator inside the refrigerator cavity. This allowed me to get access to the plugs inside the wall. I pulled the monitor plug out of the wall on the solar charge controller side. I found that the LP tank monitor wiring was a orange wire and a white wire. They had been wired wrong in the molex plug. I removed the 2 pins from the plug and flipped	

Claim : 76338

 WO # Job # Description JOB INFORMATION

them to match the wiring on the other side of the plug. Now the monitor panel works as it should. I reinstalled the monitor panels in the wall and screwed the fridge back in place.

76338 3 PANEL BOARD AT ENTRANCE BUCKLED
 Panel is bowed and popping staples out
 I pushed the panel back in and used heavier stables to hold it in place.

76338 6 SCREEN DOOR NEEDS ADJUSTED AND WILL NOT STAY SHUT
 The screen door doesn't always move with the door when opening. I adjusted the screws door handle hold back on the main door. Now the door opens and closes with the screen door every time. I checked to make sure that the screen door opens and closes on its own too. It is now working as it should.

76338 7 WHEN THE GEN IS RUNNING THE METAL HANGER FOR THE EXHAUST IS BEATING AGAINST THE FIBER GLASS
 The lower bolt was screwed into a piece of trim. Upper bolt was screwed into foam.
 I found that the upper bolt could not be tightened. There was nothing to screw to other than foam. I added a backer plate and screwed the exhaust hanger to it. This will add several more screw anchor points to prevent it from falling out or coming loose.

76338 9 THE DEAD BOLT WILL NOT LOCK
 The the door latch was hitting the striker pin wrong. I found that when closing the door, the door latch was rubbing the striker pin and would not let the door shut all the way. I removed the structure pin and added a washer behind it to space the pin out. Now the latch closes all the way without binding up halfway.

Part No	Job#	Description	PARTS	Qty	Price	Total
F100689025	4	HEATER, HOLDING TANK	50 GAL MAX,	1.00	69.71	69.71
88-8708	5	ELL 1/2 X 1/2		1.00	8.23	8.23
681487	5	1/2" BARB X 1/2	FPT SWIVEL CONE	1.00	1.99	1.99

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	4	MISC LABOUR CODE	(EXTERNAL)	0.40	185.00	74.00
Z990	4	MISC LABOUR CODE	(EXTERNAL)	0.10	185.00	18.50
Z990	5	MISC LABOUR CODE	(EXTERNAL)	0.30	185.00	55.50

Claim : 76338

```

*****
Lab Code  Job#  Description                LABOUR                Hrs      Rate      Total
*****
Z990      1   MISC LABOUR CODE (EXTERNAL)    0.00    185.00     0.00
Z990      1   MISC LABOUR CODE (EXTERNAL)    0.22    185.00    40.70
Z990      1   MISC LABOUR CODE (EXTERNAL)    0.38    185.00    70.30
Z990      3   MISC LABOUR CODE (EXTERNAL)    0.20    185.00    37.00
Z990      6   MISC LABOUR CODE (EXTERNAL)    0.20    185.00    37.00
Z990      7   MISC LABOUR CODE (EXTERNAL)    0.40    185.00    74.00
Z990      9   MISC LABOUR CODE (EXTERNAL)    0.20    185.00    37.00

```

```

*****
Excode    Job#  Description                EXTRAS                Qty      Price     Total
*****
FRT       4   UPS-TANK HEATER                1.00    15.58    15.58

```

Parts Total: 79.93
 Labour Total: 444.00
 Sublet Total: 0.00
 Extras Total: 15.58

>>>> Claim Total: 539.51

Customer Signature: _____

Date: _____