



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 76341  
Promised Date:  
24 MAY 25



### CUSTOMER WORK ORDER

WO #: 76341

Customer: 48072 - CLARK, AMANDA -  
812-629-6212

Tag:  
Author: BH  
Location: 0630 CHECK WORK

Stock #: 11575  
Stock Desc: 2025 TT COACHMEN  
CATALINA 343BHTSLE  
Chassis #: 5ZT2CAZB8SX034724  
Serial #: 5ZT2CAZB8SX034724  
Mileage: 0  
Licence:

Invoice #:  
Date In: 28 MAR 25  
Promised: 31 MAY 25  
Date Sched:  
Completed: 30 JUN 25  
Warr. Date: 10 MAY 25

#### Job #PDINTT - Internal

COMPLAINT: Transferred to BAS\*76846 on 27 MAY 25  
Estimate amount was 0.00  
PDI - NEW TRAVEL TRAILER

CAUSE: Pdi

CORRECTION: brought unit in and leveled unit then hooked to city water conection and pressurized the system to check for leaks in the put water in fresh tank and made sure the pump works properly then dewatered unit and made sure all tank sensors, water outlets/inlets were working properly and not leaking I then removed lp tanks off the front of unit and took to fill both tanks i then put tanks back on unit and made sure appliances on lp were working properly (water heater, gas range, furnace) then did lp drop test to make sure the regulator was at the right pressure then made sure there were no leaks in the system with a 5 minute hold test then made sure all 120 volt outlets, water heater, microwave, refrigerator, air-conditioner were working properly then made sure all 12 volt power lights, speakers, radio, awning, leveling system, range hood, USB, USB-C outlets were all working properly

Customer #: 48072  
CLARK, AMANDA



#### Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

#### Job #1 - Warranty

COMPLAINT: IN THE BUNK ROOM THE BIG CABINET DOOR WILL NOT CLOSE ALL THE WAY

CAUSE: Bedroom door

CORRECTION: Took screws to reattached the door to frame no issues

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	55.50



Subtotal for Job #1: 55.50

Job #2 - Warranty

COMPLAINT: ENTRY DOOR WILL NOT LATCH

CAUSE: Front door won't shut

CORRECTION: When looking at front door you could see it was off by a 1/4" so i adjusted it by taking a rubber mallet and prey bar and gently tapping on it until latch made a secured fit then i double checked my work by opening and closing 5 times to make sure it would shut correctly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	55.50

Subtotal for Job #2: 55.50

Job #3 - Warranty

COMPLAINT: FRONT SLIDE ROOM NOT COMING IN

CAUSE: Ran spins. But the room doesn't move. Ram needs replaced, Slide room 1

CORRECTION: I was doing a final inspection on this unit when I was doing so I noticed that the slide room number 1 wasn't coming in to come to find the ram was bad so m I got ahold of parts and ordered a new slide ram for unit after ordering a new one I bought in slide manually to make sure i wasn't going to damage it when taken out of my bay

Parts contacted me and said new ram is in so I put in new ram and adjusted so that the slide room would come in properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	127.65
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	57.35

Parts

Part #	Description	Qty	Price	Total
11067	40IN ACTUATOR WITH 18:1 MOTOR (VENTU	1.00	992.37	992.37

Subtotal for Job #3: 1,177.37

Job #4 - Warranty

COMPLAINT: OUTDOOR KITCHEN DOOR AND FRAME IS BENT

CAUSE: Entry door

CORRECTION: Worked on entry door to find out that it was needing adjusted so I made the proper adjustments

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	185.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Parts

Part #	Description	Qty	Price	Total
F100450203	DOOR, BAGGAGE 700 46.125 X 70.125 TH	1.00	405.95	405.95

W/O: 76341  
Promised Date: 31 MAY 25

Customer #: 48072  
CLARK, AMANDA



F100359506 SILICONE, NEUTRAL CURE SILICONE 1.00 12.09 12.09  
 10.3

**Other Services**

Code	Description	Qty	Price	Total
FRT	FREIGHT & CRATE-BAGGAGE DOOR	1.00	140.15	140.15

**Subtotal for Job #4: 743.19**

**Job #FPDINTT - Internal**

COMPLAINT: Transferred to BAS\*76846 on 27 MAY 25  
 Estimate amount was 0.00  
 FINAL PDI ON NEW TRAVEL TRAILERS

CORRECTION: completed final pdi checked the items on the sheet and made sure they worked checked outlets and the charge ports made sure the refer water heater furnace and ac operated completed gas leak check and pressured the water system.

**Labor**

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	BRM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	BRM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	BRM	N/C

**Subtotal for Job #FPDINTT: 0.00**

**Job #EQUALIZER1200 - Internal**

COMPLAINT: Transferred to BAS\*76846 on 27 MAY 25  
 Estimate amount was 0.00  
 INSTALL EQUALIZER 1200 WEIGHT DISTRIBUTION HITCH

CAUSE: Setup hitchwork

CORRECTION: I removed the hitchwork from the truck and left the old E2 hitch in the trade in. I installed a new hitch on the truck and setup the hitch high. I hooked up the truck to the trailer and adjusted the hitch as needed to work with the truck and trailer.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

**Subtotal for Job #EQUALIZER1200: 0.00**

**Job #5 - Internal**

COMPLAINT: Transferred to BAS\*76846 on 27 MAY 25  
 Estimate amount was 0.00  
 SHOCKS UNDER MAIN BED

CORRECTION: installed extra wood and moved the brackets back where it would lift the bed high secured the brackets and bed lifts easy now.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

**Subtotal for Job #5: 0.00**

**Job #6 - Internal**

Transferred to BAS\*76846 on 27 MAY 25  
 Estimate amount was 0.00

W/O: 76341  
 Promised Date: 31 MAY 25



Customer #: 48072  
 CLARK, AMANDA



Subtotal for Job #6: 0.00

Job #7 - Internal

COMPLAINT: Transferred to BAS\*76846 on 27 MAY 25  
Estimate amount was 0.00  
SWAP TV + BRACKET FROM TRADE TO LR

CAUSE: Swap the TV from the trade in and install it in the new unit. Swap the license plate from the trade in to the new unit.

CORRECTION: I swaped the TV from the trade in and install it in the new unit. I swaped the license plate from the trade in to the new unit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #7: 0.00

Job #8 - Internal

COMPLAINT: LINOLEUM HAS A SMALL HOLE NEAR THE BED BY THE CLOSET

CORRECTION: cleaned up damaged area and glued the linoleum down and rolled with roller.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

Subtotal for Job #8: 0.00

Parts Total: 1,410.41  
 Labour Total: 481.00  
 Sublet Total: 0.00  
 Extras Total: 140.15

**WORK ORDER TOTAL: 2,031.56**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 30 Jun 2025

W/O: 76341  
Promised Date: 31 MAY 25



Customer #: 48072  
CLARK, AMANDA

