

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

CLAIM STATUS Authorized
 CLAIM 2250558
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TCKV20SK092870
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 094 / 094A
 ITEM # CKT20RDSE-94
 DEALER RO # 76354
 CLAIM START DATE 04/02/2025
 CLAIM END DATE 01/01/1900

Labor rate: \$185.00

OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 70-656-01-11-003979 Furrion AC - complete - Appliances/Roof AC (Furrion)/Replace/Electrical
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2025-04-02 09:43:14 :: BAD SPOT IN THE BOARD IN THE A/C FOR THE FURNACE no power at thermostat... went into the thermostat, ac, furnace and Control Panel... ruled it back to the control board on AC. Have the 120v supply coming into the AC Board but nothing hot coming out and then found a Burnt/ Hotspot on board. Spoke with Ben and Dave who done the PDI had same issue and already replaced AC Control board. Ben said he would contract Manufacturer and to put all the screws back and things back together. PER LIPPERT THEY SAID TO REPLACE THE ENTIRE UNIT OLD Claim - 2143842 CASE 5508562
Model# FACR15HESA-PC **Dlr Sub Hrs** 2.50 **Sub Labor Amt** \$462.50
Serial# 10001771565052410010 **Appr Hrs** 2.00 **Appr Labor Amt** \$370.00
Notes
 Sent to vendor
 Authorized 2.0 hours labor for Rooftop AC and 0.50 labor on original claim for AC Control box.

Submitted Labor Amt \$462.50
 Parts & Freight \$0.00
 Total \$462.50

Approved Labor Amt \$370.00
 Parts & Freight \$0.00
 Total \$370.00

DEALER _____ DATE _____
 SIGNATURE _____
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE _____
 All repairs described have been inspected and are satisfactory.