



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 76354  
Promised Date:  
03 APR 25

### CUSTOMER WORK ORDER

WO #: 76354

Customer: 55663 - BOWEN, MEGAN -  
502-494-7576

Tag:

Author: BH

Location: 0418 SEE IF PARTS ARE  
HERE AND LET JRK KNOW IF THEY  
ARE

Stock #: 11506

Stock Desc: 2025 TT FOREST RIVER  
CHEROKEE GREY WOLF 20RDSE

Chassis #: 4X4TCKV20SK092870

Serial #: 4X4TCKV20SK092870

Mileage: 0

Licence:

Invoice #:

Date In: 29 MAR 25

Promised: 03 APR 25

Date Sched:

Completed: 17 APR 25

Warr. Date: 03 APR 25

#### Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Pdi final...

CORRECTION: Pulled unit into bay. Checked Coupling, Safety Chains and Jacks. Checked Roof. Hooked up new battery. Hooked up Shore Power Cord. Checked and adjusted Tire pressure and lug Torque. Checked brakes and all Lights. Checked all dump and low point valves and filled fresh water tank. Flushed Antifreeze from water lines and pump. Checked Fridge. Checked Converter. Checked Stovetop, Hood Vent and lights on them. Checked 120v recepticals and 12v USB ports. Checked Radio and A/B Speakers. Went to do droptest and have no power at thermostat... went into the thermostat, ac, furnace and Control Panel... ruled it back to the control board on AC. Have the 120v supply coming into the AC Board but nothing hot coming out and then found a Burnt/ Hotspot on board. Spoke with Ben and Dave who done the PDI had same issue and already replaced AC Control board. Ben said he would contract Manufacturer and to put all the screws back and things back together.

#### Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JRK	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JRK	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JRK	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JRK	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JRK	N/C

#### Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
31-1564	013-939 27-1/2" TABLE LEG	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

#### Job #BCWT - Internal

HARD WIRED BRAKE CONTROL AND WIRING - TRUCK/SUV

#### Labor

Code	Description	Mechanic	Total
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C

#### Parts

Part #	Description	Qty	Price	Total
14636	7WAY PLASTIC CAR END	1.00	N/C	N/C
19-0938	9 WAY CONNECTOR - BRACKET	1.00	N/C	N/C
19-1441	16-3030 30A CIRCUIT BREAKER	1.00	N/C	N/C



Customer #: 55663  
BOWEN, MEGAN



51146 TRIFLEX NEXT GENERATION BRAKE 1.00 N/C N/C  
 CONTRO

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

**Subtotal for Job #BCWT: 0.00**

**Job #E2 - Internal**

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: Install Equalizer hitch...

CORRECTION: Installed Plates on unit 29 in from Ball.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

**Parts**

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

**Subtotal for Job #E2: 0.00**

**Job #1 - Internal**

COMPLAINT: FIX DINNETTE

CAUSE: Fix support board on dinnette...

CORRECTION: Pulled the screw that missed the backside frame of bench. And moved it up about 1/4in so the screw would hit the frame/backside support board.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: BAD SPOT IN THE BOARD IN THE A/C FOR THE FURNACE

CAUSE: Bad board on AC, 2nd replaced...

CORRECTION: Instructed to pull a unit and board off of another unit by Ben. Pulled unit from another Grey Wolf VIN# ending in 2209 and parked unit in Walk-through. Pulled pulled bad unit and remounted good one. Hooked up and put everything back together and unit still didn't turn on. Replaced thermostat and unit now operating correctly. Received new AC unit and Control board for the unit I took parts from. Part request submitted for Thermostat i forgot to put thru. Installed new AC unit and control board.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	266.40
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	66.60
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	48.10

**Parts**

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



W/O: 76354  
 Promised Date: 03 APR 25



Customer #: 55663  
 BOWEN, MEGAN



W/O: 76354  
Promised Date: 03 APR 25

F100370210	A/C, ENHANCED SINGLE ZONE CONTROLLER	1.00	34.63	34.63
F100355723	A/C, FURRION CHILL   15K BTU AIR CON	1.00	553.13	553.13
F100355724	A/C, FURRION ENHANCED SINGLE ZONE BA	1.00	25.62	25.62

**Other Services**

Code	Description	Qty	Price	Total
FRT	UPS-CONTROLLER	1.00	15.53	15.53
FRT	FED-EX - A/C UNIT	1.00	62.00	62.00
FRT	UPS-THERMOSTAT	1.00	15.52	15.52

**Subtotal for Job #2: 1,087.53**

**Job #DELUXE - Internal**

PER DREW - DELUXE STARTER KIT

**Parts**

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

**Subtotal for Job #DELUXE: 0.00**

**Job #WALK - Internal**

COMPLAINT: WALK THRU

CAUSE: DID WALK WITH CUSTOMER AND SHOWED BC

CORRECTION: DID WALK WITH CUSTOMER AND SHOWED BC

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

**Subtotal for Job #WALK: 0.00**

Parts Total: 613.38  
Labour Total: 381.10  
Sublet Total: 0.00  
Extras Total: 93.05  
**WORK ORDER TOTAL: 1,087.53**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 17 Apr 2025



Customer #: 55663  
BOWEN, MEGAN

