



W/O: 76431
Promised Date: 20 APR 25

600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

CUSTOMER WORK ORDER

WO #: 76431 (Appointment Date: 08 APR 2025 - Time: 04:30pm)

Customer: 26619 - THOMPSON, TONY - Stock #:
(812) 677-0633 Stock Desc: 2019 TT FOREST RIVER
Tag: ALPHA WOLF 26DBHL
Author: DWS Chassis #:
Location: 0501 CHECK STATUS Serial #: 5ZT2CKRB2K2300533
Mileage:
Licence:

Invoice #: 416656
Date In: 09 APR 25
Promised: 30 APR 25
Date Sched:
Completed: 30 APR 25
Warr. Date:

Job #2 - External

COMPLAINT: CHECK SLIDE SEALS CUT

CAUSE: Sealed cracking and coming apart. Ordered new seals

CORRECTION: Removed inner and outer flap seals and installed new seals

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

Parts

Part #	Description	Qty	Price	Total
10710	25' BAL/NORCO SLIDE SEAL R854056	2.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #ROOFT - External

COMPLAINT: INSPECT ROOF AND ROOF SEAMS - CLEAN AND FILL VOIDS. 1 TUBE OF ROOF SEALANT INCLUDED.

CAUSE: Roof was dirty brown.

CORRECTION: Washed roof and then sealed any spots that needed it.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #ROOFT: 0.00

Job #1 - Warranty

COMPLAINT: RECALL 18V7522018586 AWNING ARM FASTENERS

Customer #: 26619
THOMPSON, TONY



CORRECTION: made sure each arm had 6 fasteners the front arm i had to add 1 extra screw.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	92.50

Subtotal for Job #1: 92.50

Job #TREAT - External

COMPLAINT: CLEAN AND TREAT ROOF WITH UV PROTECTANT FOR
A RUBBER , PVC, OR A TPO ROOF MEMBRANE.
DOES NOT INCLUDE "SEALING SEAMS" OR
"ROOF COATING"
WASH OUTSIDE OF CAMPER

CAUSE: Roof was really dirty

CORRECTION: Washed roof and treated.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

Parts

Part #	Description	Qty	Price	Total
6638	1 GAL RV ROOF CLEANER & PROTEC - BIO	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #TREAT: 0.00

Job #3 - External

COMPLAINT: TOUCH UP PORTIONS OF ROOF WITH DICOR NOTED TO NEED ATTENTION ON
ROOF INSPECTION.

CAUSE: Sealed rear cap and front corners.

CORRECTION: Sealed rear cap and front corners. The rest looked good.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

Subtotal for Job #3: 0.00

Parts Total: 0.00
Labour Total: 92.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 92.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited
to work performed. Consequential damages are not covered. All guaranteed work
must be completed in our service department.

W/O: 76431
Promised Date: 30 APR 25



Customer #: 26619
THOMPSON, TONY



Customer Signature : _____

Date: 10 May 2025

W/O: 76431
Promised Date: 30 APR 25



Customer #: 26619
THOMPSON, TONY

