

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 76484
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 50271 - JULIA K. PILLOW
Address: 702 W EVERGREEN RD EVANSVILLE, IN

47710

Phone: 812-760-3066

Stock Number: 11438 - 2025 CATALINA 333FKTSLE 5ZT2CAYB1SX032525

VIN: 5ZT2CAYB1SX032525 HIN: SER#: 5ZT2CAYB1SX032525

Mileage: 0 Work Order Comp: 30 APR 25

Auth. No: Dealer #:

Warr. Date: 26 APR 25 Work Order Date: 15 APR 25 Inv #: 416949

WO # Job # Description JOB INFORMATION

76484 1 FRONT SLIDE WINDOW SEAL WAS MISSING
Windows seal missing
When I got the unit in I realized it was loose so I went and got
another ladder and went to parts to get 66" for the window to get
a new seal to put on window

76484 6 THE BULB SEAL IN THE FRONT SIDE ROOM ON THE FRONT SEAL HAS A TEAR
IN IT
FOUND SEAL TORN
PULL SEAL OFF AND REINSTALL AND SEAL

76484 3 THE WALL NEXT TO THE COUCH IS BOWED
Wall board
Trim down wall board and put baton strip on.

76484 4 BUNK ROOM PASSAGE DOOR HAS SCRATCHES ON IT
Scratches on door
While I was doing my walk through i noticed that there were
scratches on door so i went over and got some touch up paint and
made the adjusted it was needing and now the door looks good as
new

76484 5 BOTTOM PULL OUT DRAWER IN THE BEDROOM IS NOT CLOSE ALL THE WAY
Drawer won't close
Took screwdriver screwed screws in drawer to insure a good fit

Claim : 76484

```

*****
WO #      Job #      Description      JOB INFORMATION
*****
76484      8      FRONT SLIDE ROOM IS TOO CLOSE AND WE CAN NOT ADJUST THE ROOM TO
FIT
Slideroom not straight
Removed bulb seal. Removed flap seal and found wall was OK.
Loosen room at gear points and move room towards the rear. Now it
fits in the front. But the wall on the rear is not square.
Removed inside trim and outside wall board. Took screw out of
floor and screwed wall back straight. Put trim back and putty
holes. Put flap seal back and bulb seal. Taped off and siliconed.

```

```

*****
Part No      Job#      Description      PARTS      Qty      Price      Total
*****
538578      1      Seal - Black Window Glazing - 85/      6.00      1.36      8.16
338809      6      Seal - D Seal - EK - Modified      8.00      0.97      7.76

```

```

*****
Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total
*****
Z990      1      MISC LABOUR CODE (EXTERNAL)      0.00      185.00      0.00
Z990      1      MISC LABOUR CODE (EXTERNAL)      0.30      185.00      55.50
Z990      6      MISC LABOUR CODE (EXTERNAL)      0.00      185.00      0.00
Z990      6      MISC LABOUR CODE (EXTERNAL)      0.50      185.00      92.50
Z990      6      MISC LABOUR CODE (EXTERNAL)      0.50      185.00      92.50
Z990      3      MISC LABOUR CODE (EXTERNAL)      0.75      185.00      138.75
Z990      4      MISC LABOUR CODE (EXTERNAL)      0.10      185.00      18.50
Z990      5      MISC LABOUR CODE (EXTERNAL)      0.20      185.00      37.00
Z990      8      MISC LABOUR CODE (EXTERNAL)      1.50      185.00      277.50
Z990      8      MISC LABOUR CODE (EXTERNAL)      0.00      185.00      0.00
Z990      8      MISC LABOUR CODE (EXTERNAL)      1.50      185.00      277.50

```

```

Parts Total:      15.92
Labour Total:      989.75
Sublet Total:      0.00
Extras Total:      0.00

```

>>>> Claim Total: 1,005.67

Customer Signature: _____

Date: _____