

Pre-Authorization

Pre-Authorization number PA03841442 Reference no: 76507 Status: Approved Approved by stept
 Servicing Name Address VIN Retail sold on Approved date 4/22/2025
 Dealer

1194 Basden's American RV Basden's American RV 4YDFCGR20R2502343 4/26/2024
 600 E Baseline Rd
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2104808B	Slide Out - Box - 5	0.00	4.00	4.00		1	2.00	Complaint:THE BOTTOM OF THE BED ROOM SLIDE IS STARTING TO CRACK AND CUSTOMER WANTS TO KNOW WHY AND HOW WE CAN FIX THIS Cause:Plastic plate cover is cracked Correction:Took pictures of the crack on the bottom side of the slideroom. Put in po fro a new plastic floor cover.
2	3201606B	Batten Tape - Rep	0.00	0.20	0.20		1	0.20	Complaint:CHECK TRIM ON WALL BY STEPS TO BEDROOM ON RIGHT SIDE Cause:Seam tape not holding to the wall Correction:Took pictures of the seam tape not holding
					<u>4.20</u>	<u></u>			

Pre-Authorization number PA03841442

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return toKeystone RV Company