



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76557
Promised Date:
04 APR 25

CUSTOMER WORK ORDER

WO #: 76557

Customer: 55742 - WOLFE, CARL -
270-952-6571

Tag:

Author: BH

Location: 0707 CHECK WORK

Stock #: 11582

Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 271DBS

Chassis #: 5ZT2CASB2SU046038

Serial #: 5ZT2CASB2SU046038

Mileage: 0

Licence:

Invoice #:

Date In: 22 APR 25

Promised: 29 APR 25

Date Sched:

Completed: 30 JUN 25

Warr. Date: 29 APR 25

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*76628 on 30 APR 25

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

CAUSE: Pdi

CORRECTION: Checked appliances brakes tire pressure torqued lugs checked electrical system and plumbing system checked cabinets doors and drawers. Filled l.p tanks and ran l.p drop test. Documented model and serial numbers. Removed packaging from appliances.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z991 | MISC LABOUR CODE (INTERNAL) | ZMS | N/C |
| Z991 | MISC LABOUR CODE (INTERNAL) | ZMS | N/C |
| Z991 | MISC LABOUR CODE (INTERNAL) | ZMS | N/C |

Other Services

| Code | Description | Qty | Price | Total |
|------|-----------------|------|-------|-------|
| SS | SHOP SUPPLIES | 0.00 | N/C | N/C |
| LPGI | LP - UNIT SALES | 0.00 | N/C | N/C |

Subtotal for Job #PDINTT: 0.00

Job #FPDINTT - Internal

COMPLAINT: Transferred to BAS*76628 on 30 APR 25

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final.

CORRECTION: Ran l.p. drop test installed battery. Checked all appliances.

Labor

| Code | Description | Mechanic | Total |
|--------|--------------------------|----------|-------|
| PDINTT | PDI - NEW TRAVEL TRAILER | ZMS | N/C |
| PDINTT | PDI - NEW TRAVEL TRAILER | ZMS | N/C |
| PDINTT | PDI - NEW TRAVEL TRAILER | ZMS | N/C |

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

COMPLAINT: Transferred to BAS*76628 on 30 APR 25

Estimate amount was 0.00

10K E2 EQUALIZER HITCH



Customer #: 55742
WOLFE, CARL





CAUSE: Hitch install.

CORRECTION: Installed hitch brackets to unit. Placed the rest of the hitch inside the unit. installed hitch to unit.

| Labor | | | |
|--------------|-----------------------------|----------|-------|
| Code | Description | Mechanic | Total |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | N/C |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | N/C |

| Other Services | | | | |
|------------------------------|---------------|------|-------|-------------|
| Code | Description | Qty | Price | Total |
| SS | SHOP SUPPLIES | 0.00 | N/C | N/C |
| Subtotal for Job #E2: | | | | 0.00 |

Job #1 - Internal

COMPLAINT: Transferred to BAS*76628 on 30 APR 25
 Estimate amount was 0.00
 THE FREEZER DOOR NEEDS TO BE ADJUSTED.

CAUSE: The is hitting the latch and needs to be raised up.

CORRECTION: Took a plastic washer and cut a section out of it. Placed the washer under the freezer door post to raise it up. Doors is now shutting correctly.

| Labor | | | |
|-----------------------------|-----------------------------|----------|-------------|
| Code | Description | Mechanic | Total |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | N/C |
| Subtotal for Job #1: | | | 0.00 |

Job #5 - Warranty

COMPLAINT: THE BATHROOM NOT BEDROOM DOOR NEEDS TO

CAUSE: BE
 ADJUSTED

CORRECTION: Door will not latch. The latch was positioned incorrectly and was bent. Removed the latch and straightened the latch and sanded excess wood where the latch sits. Installed latch. Door latches as it should.

| Labor | | | |
|-----------------------------|-----------------------------|----------|--------------|
| Code | Description | Mechanic | Total |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 37.00 |
| Subtotal for Job #5: | | | 37.00 |

Job #6 - Warranty

COMPLAINT: THE TRIM ON THE BIG DOOR OF THE ENTERTAINMENT CENTER IS MISALIGNED

CAUSE: Trim
 is loose.

CORRECTION: Secured trim with Brad nails

| Labor | | | |
|--------------|-----------------------------|----------|-------|
| Code | Description | Mechanic | Total |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 18.50 |



Subtotal for Job #6: 18.50

Job #8 - Warranty

COMPLAINT: ONE OF THE DECALS IS BROKEN AND NEEDS REPLACED

CAUSE: There is a hole in the back of the decal. Need to replace the decal. Black "summit series "

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | BB | 92.50 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 0.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 0.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | 0.00 |

Parts

| Part # | Description | Qty | Price | Total |
|------------|--------------------------------------|------|-------|-------|
| F100597137 | GRAPHIC, #44 "SUMMIT SERIES" SIDE MI | 1.00 | 10.57 | 10.57 |
| F100418468 | GRAPHIC | 1.00 | 5.14 | 5.14 |

Other Services

| Code | Description | Qty | Price | Total |
|------|-------------------|------|-------|-------|
| FRT | UPS-MOTOR&GRAPHIC | 1.00 | 15.51 | 15.51 |
| FRT | UPS-DECAL | 1.00 | 15.65 | 15.65 |

Subtotal for Job #8: 139.37

Job #9 - Warranty

COMPLAINT: THERE ARE BUBBLES IN THE DECALS ON THE OFF DOOR SIDE

CAUSE: Bubbles in decals.

CORRECTION: Popped holes near bubbles and smoothed out with a rag and soapy water

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 92.50 |

Subtotal for Job #9: 92.50

Job #10 - Warranty

COMPLAINT: THERE ARE BUBBLES IN THE DECAL ON THE DOOR SIDE

CAUSE: Bubbles in decal

CORRECTION: Popped bubbles and smoothed out with a rag and soapy water.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 55.50 |

Subtotal for Job #10: 55.50

Job #11 - Warranty

COMPLAINT: THE FRONT SCREEN NEEDS TO BE ADJUSTED

CAUSE: Screen door latch isn't holding the door.

CORRECTION: Removed latch. Installed 2 washers to push latch closer to the

W/O: 76557
Promised Date: 29 APR 25



Customer #: 55742
WOLFE, CARL



door.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 37.00 |

Subtotal for Job #11: 37.00

Job #12 - Warranty

COMPLAINT: THE FRONT DOOR SIDE JACK IS NOT WORKING.

CAUSE: When running the Jack's only one side goes down. Motor started to smoke on the passenger side. Motor is locked up. It will not move on manually either.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | 92.50 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 0.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 0.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 0.00 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | 0.00 |

Parts

| Part # | Description | Qty | Price | Total |
|------------|--------------------------------------|------|-------|-------|
| F100516332 | MOTOR ONLY FOR BAL AUTO LEVELING JAC | 1.00 | 91.08 | 91.08 |

Subtotal for Job #12: 183.58

Job #13 - Warranty

COMPLAINT: SLIDE SKIS ARE NOT SECURE ON THE SLIDE ROOM

CAUSE: Slide skis aren't secure to the floor.

CORRECTION: Applied 3m tape to the skis and placed a jack with x 2x6 to support the skis. Removed posts the next morning. Skis are secured.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 70.30 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 20.35 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 1.85 |

Subtotal for Job #13: 92.50

Job #14 - Warranty

COMPLAINT: DENT ON THE FREEZER DOOR

CAUSE: Dent on freezer. Took pictures and filled out parts request.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | 72.15 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 18.50 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK | 1.85 |

Parts

| Part # | Description | Qty | Price | Total |
|------------|--------------------------------------|------|--------|--------|
| F100282071 | GE STAINLESS FREEZER DOOR 2022 FOR | 1.00 | 426.94 | 426.94 |

Other Services

| Code | Description | Qty | Price | Total |
|------|-----------------------|------|-------|-------|
| FRT | SHIPPING-FREEZER DOOR | 1.00 | 10.66 | 10.66 |

Subtotal for Job #14: 530.10

W/O: 76557
Promised Date: 29 APR 25



Customer #: 55742
WOLFE, CARL





Job #15 - Warranty

COMPLAINT: WALL PANEL IS LOOSE IN THE BEDROOM DOOR SIDE

CAUSE: Panel came loose from the wall stud.

CORRECTION: Secured with staples and filled staple holes with putty.

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS | 37.00 |

Subtotal for Job #15: 37.00

Job #16 - Warranty

Transferred to BAS*77031 on 16 JUN 25
Estimate amount was 0.00
WATER HEATER SHOT BLUE FLAMES OUT THE EXHAUST AND ELECTRIC DOESNT WORK AT ALL.

Subtotal for Job #16: 0.00

Job #17 - Warranty

Transferred to BAS*77031 on 16 JUN 25
Estimate amount was 0.00
DINETTE TABLE WILL NOT FIT IN THE DOWN POSITION. (BED)

Subtotal for Job #17: 0.00

Job #18 - Warranty

Transferred to BAS*77031 on 16 JUN 25
Estimate amount was 0.00
PANTRY SHELVES ARE DROOPING/BOWING

Subtotal for Job #18: 0.00

Job #19 - Warranty

Transferred to BAS*77031 on 16 JUN 25
Estimate amount was 0.00
CUP HOLDER ON COUCH IS SCRATCHED

Subtotal for Job #19: 0.00

Job #20 - Warranty

Transferred to BAS*77031 on 16 JUN 25
Estimate amount was 0.00
REAR ENTRYDOOR DOES NOT LATCH EASILY. REALLY HAVE TO PUSH HARD OR SLAM.



Subtotal for Job #20: 0.00

Job #21 - Warranty

Transferred to BAS*77031 on 16 JUN 25
Estimate amount was 0.00
SPOTS ON BOTH ENTRYDOORS GLASS WILL NOT
COME OFF.

Subtotal for Job #21: 0.00

Job #22 - External

Transferred to BAS*77031 on 16 JUN 25
Estimate amount was 0.00
CUSTOMER WANTS ESTIMATE FOR ADDING
BANNISTER RAIL TO REAR ENTRY DOOR.

Subtotal for Job #22: 0.00

| | |
|--------------------------|-----------------|
| Parts Total: | 533.73 |
| Labour Total: | 647.50 |
| Sublet Total: | 0.00 |
| Extras Total: | 41.82 |
| WORK ORDER TOTAL: | 1,223.05 |

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 Jul 2025

W/O: 76557
Promised Date: 29 APR 25



Customer #: 55742
WOLFE, CARL

