



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76564
Promised Date:
20 APR 25

CUSTOMER WORK ORDER

WO #: 76564

Customer: 3801 - FIFIELD, MICHAEL -
270-993-3819

Tag:

Author: BH

Location: 0605 CHECK WORK

Stock #: 11586

Stock Desc: 2025 TT ALLIANCE RV

DELTA 262RB

Chassis #: 7M5TD2924SC306309

Serial #: 7M5TD2924SC306309

Mileage: 0

Licence:

Invoice #:

Date In: 23 APR 25

Promised: 29 APR 25

Date Sched:

Completed: 28 MAY 25

Warr. Date: 29 APR 25

Job #PDINTT - Internal

Transferred to BAS*76674 on 05 MAY 25

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #FPDINTT - Internal

Transferred to BAS*76674 on 05 MAY 25

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	SAR	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	SAR	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	SAR	N/C

Subtotal for Job #FPDINTT: 0.00

Job #SWAP - Internal

Transferred to BAS*76674 on 05 MAY 25

Estimate amount was 0.00

SWAP CUSTOMER'S HITCHWORK

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #SWAP: 0.00



Customer #: 3801
FIFIELD, MICHAEL



Job #COVER-L - Internal

Transferred to BAS*76674 on 05 MAY 25
 Estimate amount was 0.00
 INSTALL LARGE SLIDE COVER 138" TO 192"

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #COVER-L: 0.00

Job #1 - Warranty

COMPLAINT: THE BLACK TANK BREAKER IS INSTALLED BACKWARDS

CAUSE: Black tank vacuum breaker

CORRECTION: During the pdi I connected the garden hose to the black tank flush connection. The garden hose was tight from pressure and couldn't hear water flowing. Went to the vacuum breaker and the valve wasn't up. Shut off the water to the black tank flush and disconnected the hose to relieve the pressure. Unscrewed the vacuum breaker and cut the bands on the pex lines. Pulled off the fittings and cut the opposite water short. Crimped the fittings to the correct water line and screwed on the vacuum breaker. Went back to the black tank flush connection and tightened the hose, turned on the water and could hear water flowing thru the vacuum breaker and into the black tank. Turned off the water and disconnected the hose from the black tank flush.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	29.60
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	3.70

Subtotal for Job #1: 33.30

Job #2 - Warranty

COMPLAINT: THE SCREEN DOOR NEEDS ADJUSTED

CAUSE: Screen door latch

CORRECTION: During the pdi checked the entry door and screen door to verify they close properly. The screen door didn't catch the latch. Took pictures of the problem. Unscrewed the latch and replaced with longer screws and 4 washers. Put the washers behind the latch and screwed in longer screws as the factory screws were too short. Shut the screen door and found that it closes and stays closed till it is opened as should.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	18.50

Subtotal for Job #2: 18.50

Job #3 - Warranty

COMPLAINT: THE SLIDE ROOM TRACK IS HITTING THE SLIDE SEAL.

CAUSE: Flap seal hits bell

CORRECTION: Took pictures of the slideroom bell hitting the flap seal. Used a razor blade to trim the flap seal till the slideroom bell cleared. Ran the slideroom in and out to verify the bell would not hit the flap seal.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Z990	MISC LABOUR CODE (EXTERNAL)	SAR	37.00
Subtotal for Job #3:			37.00

Job #4 - Warranty

COMPLAINT: STYLE IS DAMAGED ON THE DINETTE SEAT

CAUSE: Style frame on the dinette is damaged from the folding table on the side of the kitchen counter and has a long scratch

CORRECTION: Took pictures of the dinette booth that has damage. Put in po for new frame style

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Parts

Part #	Description	Qty	Price	Total
20163	Stile - 2.5 x 108 - LC Square - Ello	1.00	8.99	8.99

Other Services

Code	Description	Qty	Price	Total
FRT	FRIGHT - 4 & 6	1.00	33.62	33.62

Subtotal for Job #4: 98.11

Job #5 - Internal

COMPLAINT: CHECK SILICONE ON REAR OF UNIT

CAUSE: Left rear corner trim was missing silicone from about the middle to the roof

CORRECTION: Place tape to the rear corner to show were there was no silicone and silicone. Applied silicone to the corner trim that was missing silicone. Took pictures of the corner trim.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: DECAL ON THE OFF DOOR SIDE FRONT IS PEELING

CAUSE: Black decal is peeling up

CORRECTION: Took pictures of the decal that is peeling put in po for a new decal.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	92.50
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Parts

Part #	Description	Qty	Price	Total
25226	Decal - DC 5A LH - (Delta 2024)	1.00	21.99	21.99

Subtotal for Job #6: 114.49

W/O: 76564
Promised Date: 29 APR 25



Customer #: 3801
FIFIELD, MICHAEL



W/O: 76564
Promised Date: 29 APR 25



Customer #: 3801
FIFIELD, MICHAEL



Parts Total:	30.98
Labour Total:	236.80
Sublet Total:	0.00
Extras Total:	33.62
WORK ORDER TOTAL:	301.40

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 May 2025

