



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76572
Promised Date:
26 APR 25



CUSTOMER WORK ORDER

WO #: 76572 (Appointment Date: 23 APR 2025 - Time: 02:00pm)

Customer: 55707 - MIDDENDORF, ERIC
- (812) 455-1466

Tag:
Author: BJW

Location: 0505 BH TO CLOSE

Stock #:
Stock Desc: 2022 5W KEYSTONE
RAPTOR 362
Chassis #:
Serial #: 4YDFRPT24NR801021
Mileage:
Licence:

Invoice #: 417154
Date In: 23 APR 25
Promised: 30 APR 25
Date Sched:
Completed: 10 MAY 25
Warr. Date:

Job #1 - External

COMPLAINT: REAR CARGO DOOR WILL NOT UNLOCK

CAUSE: Pulled manual override and opened rear door. Removed cover plate for switch/lock mechanism. Switch Tested good and switch has proper voltage coming to it. Installed cover plate. Shut door and operated lock. Door didn't unlock immediately.

CORRECTION: Moved a ladder over to the unit. Held the door slightly open and applied silicone lubricant to latches and locking pins. Shut door and let sit for a minute. Opened door with keys multiple times in a row. Cleaned up mess.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Subtotal for Job #1:			0.00

Job #2 - Warranty

COMPLAINT: THERE IS A WEATHERSTRIP ACROSS THE BOTTOM OF THE OPENING FOR THE TOY HAULER DOOR THAT IS TORN ON THE OFF DOOR SIDE. CUSTOMER SHOWED BJ THAT THE PORCH WALLS ARE HITTING THE WEATHERSTRIP WHEN TAKING THEM IN AND OUT AND IT IS RIPPING THE WEATHERSTRIP.

CAUSE: Rubber seal is torn on the rear door.

CORRECTION: Removed damaged seal. Received new seal from parts. Cut to length. Applied 3m adhesive primer and installed seal. Cleaned up mess and parked unit.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	91.80
Z990	MISCELLANEOUS REPAIR	ZMS	50.40
Z990	MISCELLANEOUS REPAIR	ZMS	37.80

Parts

Part #	Description	Qty	Price	Total
211927	Seal - "D" - 5/8" Large Foam - Black	8.00	1.51	12.08
Subtotal for Job #2:				192.08

Job #SUMMER - External

COMPLAINT: DE-WINTERIZE UNIT

CAUSE: Dewinterize

Customer #: 55707
MIDDENDORF, ERIC



CORRECTION: Pulled unit into shop. Hooked up to city water. Ran the toilet, shower, bathroom faucet and the kitchen faucet and the garagehook ups. . Then outside and ran the outside faucet. Lines flowed good with no issues.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #SUMMER: 0.00

Job #4 - External

COMPLAINT: BOTH EXTERIOR HANDLES ON THE ENTRY DOORS HANG UP AND CAN BE DIFFICULT TO GET TO RELEASE TO OPEN THE DOORS.

CAUSE: There was a shipping block on the rear door.

CORRECTION: Removed block. Applied silicone spray to both doors. Both doors are opening easily.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

Subtotal for Job #4: 0.00

Parts Total:	12.08
Labour Total:	180.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	192.08

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 May 2025

W/O: 76572
Promised Date: 30 APR 25



Customer #: 55707
MIDDENDORF, ERIC

