

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2282328
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CARB1SU045761
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT261BHS-8
ALLEN R DUKE		DEALER RO #	76599
7954 LYDDANE BRIDGE RD S		CLAIM START DATE	04/30/2025
Owensboro, KY 42301		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	04/12/2025	WARRANTY EXPIRATION DATE	04/12/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-43-19-00-001109	Gutter Rail - Exterior/Exterior Miscellaneous/Reseal/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-04-30 11:16:52 :: CUSTOMER ADVISES THAT WATER RUNS DOWN THE SIDE OF THE CAMPER BETWEEN THE GUTTER AND THE SIDEWALL. Assess leak at gutters and sidewall. After looking over gutters system, gutters seams where 2 separate pieces meet aren't sealed properly. One of the gutters (doorside) also had black dicor built up in gutter at seam which i cleaned out and sealed the bottom of gutters at seams.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	30-102-08-00-002279	Wall Panel - Interior/Panels, Ceilings, & Interior Moldings/Overlay/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-04-30 11:17:25 :: THE WALL BY THE DINETTE HAS WALL PAPER THAT WON'T STAY STUCK DOWN. THE PIECE ON THE WALL BY THE BATHROOM IS LOOSE AND NOT SECURED Assess wallpaper by dinette and wall by bathroom... Area by dinnette was actually a loose wall panel, which i removed the seam tape and stapled panel back into stud and reapplied seam tape. The 1.5ft section of wall panel between the bathroom door and dinnette has a little flimse to it but due to no stud in this section it can't be reinforced in the middle but all edges are secured.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50
	Notes			
	AUTHORIZED AS SUBMITTED			

Submitted	Labor Amt	\$92.50	Approved	Labor Amt	\$92.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$92.50		Total	\$92.50

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.