



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76637
Promised Date:
24 MAY 25

CUSTOMER WORK ORDER

WO #: 76637

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0515 CHECK PREAUTH

Stock #: 11591
Stock Desc: 2025 TT ALLIANCE RV
DELTA 262RB
Chassis #: 7M5TD2923SC306379
Serial #: 7M5TD2923SC306379
Mileage: 0
Licence:

Invoice #:
Date In: 01 MAY 25
Promised: 31 MAY 25
Date Sched:
Completed: 14 MAY 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: VIN check, checked all of the following condition of the battery and battery cables and connections, condition of the trailer coupler, the safety chain, operation of the tongue jack, running lights, brake lights, and turn signals, breakaway cable and brakes, Plug in the shore power cord, fresh water drain caps, wastewater cap and close waste system valves, inspect brake wires, shackles, axle, LP lines and clamp spacing, the underbelly for holes, gaps, and loose materials, Pressurize the city water system and check for leaks/missing caps on drain lines.. Inspect and clean out exterior appliance compartments (refrigerator, water heater, furnace), performed a lp drop test and checked for leaks in lines, Check exterior lights, windows and vents for fit and finish.. Inspect storage compartment, emptied black and grey

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: BATH ROOM FAN NOT WORKING

CAUSE: Bathroom fan and rear camera tide on the same circuit
Fan not working

CORRECTION: Connected a tone generator to the wires at the bathroom fan and chased down the wire. Found the wire connected to the backup camera switch. When the camera is on the bathroom fan works. Camper has no camera installed.
I pulled off the fan to chase the pink and white wire down to the fuse box. Check the fuses all the fuses were good unplugged the pink and wipe cord to chase it down into the ceiling to the fan to come to realize that it was not properly installed. So I installed it correctly and now the fan is working



Customer #: 1000
BASDEN'S AMERICAN RV,



Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	20.35
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	72.15

Subtotal for Job #1: 92.50

Parts Total: 0.00
Labour Total: 92.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 92.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 14 May 2025

W/O: 76637
Promised Date: 31 MAY 25



Customer #: 1000
BASDEN'S AMERICAN RV,

