

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2303722
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CABCXSK011204
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	203 / 203
OWNER INFORMATION		ITEM #	BCAT134RKX
PAUL H MCCORMIK		DEALER RO #	76638
1017 ALLENS LANE		CLAIM START DATE	05/19/2025
Evansville, IN 47710		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	05/30/2025	WARRANTY EXPIRATION DATE	05/30/2026

Claim Line Details

Labor

Line# 1	Operation Code 20-66-02-00-000664	Operational Description Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-05-19 13:34:35 :: THE ENTRY DOOR HITS THE FRAME WHEN CLOSING AND IT DOES NOT CLOSE ALL THE WAY. Entry door When opening and closing the door the frame is rubbing and so I had to readjust the frame and also position of where the latch goes and now the door shuts properly			
Model#		Dlr Sub Hrs	0.30	Sub Labor Amt \$55.50
Serial#		Appr Hrs	0.30	Appr Labor Amt \$55.50
	Notes			

Labor

Line# 2	Operation Code 40-197-01-11-001326	Operational Description 30 or 50 Amp Shore Power Cord - Detachable - Electrical/110 Volt Exterior/ Replace/Electrical		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-05-19 13:35:28 :: THIS UNIT IS MISSING A 30 AMP SHORE POWER CORD UNIT IS MISSING A 30 AMP TWIST CORD			
Model#		Dlr Sub Hrs	0.10	Sub Labor Amt \$18.50
Serial#		Appr Hrs	0.00	Appr Labor Amt \$0.00
	Notes PARTS ONLY AUTHORIZED			

Labor

Line# 3	Operation Code 20-58-01-00-000608	Operational Description Metal - Aluminum Siding, each sheet - Exterior/Metal, Aluminum Siding/Replace/ No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-05-19 13:36:34 :: THERE IS A DENT ON THE NOSE CAP. Dent in nose cap When looking at the picture submitted the dent is in the smaller circle the dent isn't noticed until you rub your hand over it and can feel it and see it WILL NEED TO REMOVE THE METAL AND REINSTALL NEW WITH DECALS PLEASE ADVISE			
Model#		Dlr Sub Hrs	7.00	Sub Labor Amt \$1,295.00
Serial#		Appr Hrs	4.50	Appr Labor Amt \$832.50
	Notes EXCESSIVE AMOUNT REQUESTED. CHANGED TO SIMILAR REPAIR TIME			

Submitted

Labor Amt
Parts & Freight
Total

\$1,369.00
\$0.00
\$1,369.00

Approved

Labor Amt
Parts & Freight
Total

\$888.00
\$0.00
\$888.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.