



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76643
Promised Date:
24 MAY 25

CUSTOMER WORK ORDER

WO #: 76643

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0619 BH TO CLOSE

Stock #: 11597
Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 221EPIC
Chassis #: 5ZT2CALB1SU046143
Serial #: 5ZT2CALB1SU046143
Mileage: 0
Licence:

Invoice #:
Date In: 01 MAY 25
Promised: 31 MAY 25
Date Sched:
Completed: 27 JUN 25
Warr. Date:

Job #PDINTT - Internal

Transferred to BAS*76938 on 04 JUN 25
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: CABINET DOOR HANDLE IS STRIPPED AND NEEDS REPLACED

CAUSE: Cabinet door

CORRECTION: Cabinet door handle is loose come to find out the handle screws are stripped causing the doors to not shut properly needing to order new handle and screws for door to shut properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Parts

Part #	Description	Qty	Price	Total
F100425383	PULL, CABINET DOOR MATTE BLACK MC 20	1.00	1.22	1.22

Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 76643
Promised Date: 31 MAY 25



Customer #: 1000
BASDEN'S AMERICAN RV,



Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	15.57	15.57
Subtotal for Job #1:				35.29

Job #2 - Warranty

COMPLAINT: BATHROOM DOOR WILL NOT SHUT

CAUSE: Door wouldnt shut

CORRECTION: I had to readjusted the door and had to cut on the frame and make a new place for the latch to set into and also make the handle tighter for the latch to close correctly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00
Subtotal for Job #2:			37.00

Job #3 - Warranty

COMPLAINT: KITCHEN TOWL RACK IS STRIPPED

CAUSE: Kitchen towel holder

CORRECTION: The kitchen towel holder was loose on the cabinet so I had reposition it and also find some spray adhesive for it not to come down again so now it's holding better

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Parts

Part #	Description	Qty	Price	Total
F100607628	HOLDER, PAPER TOWEL SBCPTH1	1.00	4.14	4.14
Subtotal for Job #3:				22.64

Job #4 - Warranty

COMPLAINT: STAIN ON THE COUCH

CAUSE: Stain

CORRECTION: I took some stain remove and removed the stain from the couch but had to scrub awhile because it was deep in the fabric so I had to find a brush and use that to remove the stain with cleaner

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50
Subtotal for Job #4:			18.50

Job #5 - Warranty

COMPLAINT: HUB COVER CAME OFF OF THE DOOR SIDE FRONT WHEEL

CAUSE: Hub

CORRECTION: The wheels hub is off and needing to order a new one waiting on parts

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	92.50





Subtotal for Job #5: 92.50

Job #6 - Warranty

COMPLAINT: HUB CAP MISSING CAP ON DOOR SIDE FRONT

CAUSE: Center cap

CORRECTION: Took off tire to find out that the chrome center cap is completely missing

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	9.25
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00

Parts

Part #	Description	Qty	Price	Total
F100169891	SNAP IN CHROME CENTER CAP PLUG	1.00	1.33	1.33
F100330779	CENTER CAP, 3.195 OPEN STAINLESS STE	1.00	5.13	5.13

Subtotal for Job #6: 15.71

Job #7 - Warranty

COMPLAINT: ENTRY DOOR WILL NOT SHUT

CAUSE: Entry door

CORRECTION: Moved the screws over and also adjusted the frame a slight bit now door shuts with no issues

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	55.50

Subtotal for Job #7: 55.50

Job #8 - Warranty

COMPLAINT: THE AWNING JUST COMES OUT AFTER LETTING GO OF THE BUTTON

CAUSE: Awning unfolding

CORRECTION: When running awning in and out the awning will unravel itself but when you run it back in it will be fine so I adjusted the left side and right side and now the awning is working properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	55.50

Subtotal for Job #8: 55.50

Parts Total: 11.82
 Labour Total: 305.25
 Sublet Total: 0.00
 Extras Total: 15.57
WORK ORDER TOTAL: 332.64



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 27 Jun 2025

Customer Signature : _____

W/O: 76643
Promised Date: 31 MAY 25



Customer #: 1000
BASDENS AMERICAN RV,



Customer Work
Order

