



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76657
Promised Date:
08 MAY 25

CUSTOMER WORK ORDER

WO #: 76657

Customer: 55757 - WHEELER,
JONATHAN M. - 812-456-1847

Tag:

Author: BH

Location: 0520 CHECK WORK

Stock #: 11501

Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 271DBS

Chassis #: 5ZT2CASB3SU044881

Serial #: 5ZT2CASB3SU044881

Mileage:

Licence:

Invoice #:

Date In: 05 MAY 25

Promised: 08 MAY 25

Date Sched:

Completed: 19 MAY 25

Warr. Date: 08 MAY 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final

CORRECTION: Brakes checked, emergency barke checked. Exterior lights all checked out except right rear light on back. Lug nuts properly torqued. Correct air pressure in all 5 tires. Electrical stabilizer jack work properly. Installed Equalizer hitch. Roof inspection done. All outlets worked. Ran water in all faucets toilet and shower to clear the lines. Checked ac and heater. Refrigerator and freezer works outside Refrigerator checked good. Stove and microwave was good tv and radio checked good. Water pump works properly. Awning checked good.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #EQUALIZER1000 - Internal

COMPLAINT: INSTALL 1000# EQUALIZER HITCH

CAUSE: Setup hitch height and hook up to trailer

CORRECTION: I setup the hitch height. I hooked up to the trailer. I adjusted hitchwork as needed. Truck could use some spring help and tires.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
710831	EQUALIZER 1000#/10000# ADJ. HITCH	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C



Customer #: 55757
WHEELER, JONATHAN M.



Subtotal for Job #EQUALIZER1000: 0.00

Job #DELUXE - Internal
DELUXE STARTER KIT

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #1 - Warranty

COMPLAINT: RIGHT REAR MARKER LIGHT IS HALF FULL OF WATER AND NOT WORKING

CAUSE: Right rear marker light 1/2 full of water

CORRECTION: Replaced right rear marker light that was 1/2 full of water and didn't work. Installed a new marker light and after install it works properly.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00

Part #	Description	Qty	Price	Total
11075	LIGHT, CLEARANCE RED SURFACE MOUNT L	1.00	1.99	1.99

Other Services Code	Description	Qty	Price	Total
FRT	UPS-LIGHT	1.00	15.51	15.51

Subtotal for Job #1: 54.50

Parts Total: 1.99
Labour Total: 37.00
Sublet Total: 0.00
Extras Total: 15.51
WORK ORDER TOTAL: 54.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 19 May 2025

W/O: 76657
Promised Date: 08 MAY 25



Customer #: 55757
WHEELER, JONATHAN M.

