

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2299825
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKE27SX164845
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKT29TE
SARAH L GOUGH		DEALER RO #	76664
8545 GREENDALE DR		CLAIM START DATE	05/15/2025
Evansville, IN 47711		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	05/10/2025	WARRANTY EXPIRATION DATE	05/10/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-44-19-00-000553	Roof Moldings - Front or Rear - Exterior/Roof/Reseal/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-05-15 09:09:37 :: THERE ARE SOME VOIDS IN THE DICOR ON THE ROOF Voids in sealer Filled voids in sealer with Dicor self-leveling			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$37.00
	Serial#	Appr Hrs	0.20	Appr Labor Amt \$37.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	20-69-02-17-000708	Compartment Door Lock or Slam Latch - Exterior/Compartment Doors/Adjust/Latch		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-05-15 09:32:41 :: THE COMPARTMENT DOOR ON THE OFF DOOR REAR HAS A NUT ON THE LOCK CYLINDER THAT WAS NOT IN PLACE. Side compartment lock had vibrated off Side come compartment lock latch on inside vibrated off and couldn't open door so I had to take floor out from under bunk together door open. So I put silicone on the srew so it won't vibrate loose and reinstalled floor under bunk			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
Notes				

Labor

Line# 3	Operation Code	Operational Description		
	60-138-01-00-001527	Termination Valve Cable with Removal Of Underbelly - Plumbing/Drainage System/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-05-15 09:33:48 :: THE FRESH WATER DUMP VALVE IS LEAKING Fresh water dump valve leaking Pulled under penning down to pin point the leak. Found out that it was coming from the fresh water shut off. I unscrewed the shut off and found there was was no thread tape or thread dope. So I cleaned it and put thread dope on threads.			
Model#	Dlr Sub Hrs	1.00	Sub Labor Amt	\$185.00
Serial#	Appr Hrs	1.00	Appr Labor Amt	\$185.00
	Notes			
	Authorized as requested.			

Submitted	Labor Amt	\$259.00
	Parts & Freight	\$0.00
	Total	\$259.00

Approved	Labor Amt	\$259.00
	Parts & Freight	\$0.00
	Total	\$259.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.