



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76743
Promised Date:
12 MAY 25

CUSTOMER WORK ORDER

WO #: 76743

Customer: 55792 - GALMICHE,
RAYMOND - 270-485-6598

Tag:

Author: BH

Location: 0523 BH TO CLOSE

Stock #: 11453

Stock Desc: 2025 TT KEYSTONE

SPRINGDALE 260BHC

Chassis #: 4YDTSGL29S7100683

Serial #: 4YDTSGL29S7100683

Mileage:

Licence:

Invoice #:

Date In: 12 MAY 25

Promised: 15 MAY 25

Date Sched:

Completed: 28 MAY 25

Warr. Date: 15 MAY 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Installed battery, checked all exterior lights brake lights, brakes and Emergency Brakes all work properly. Torqued all lug nuts to spec. Checked air pressure in all 5 tires. Roof inspection found some small voids in the sealer filled them with Dicor self-leveling. Checked all outlets and interior lights they work properly. Hooked to city water cleared lines. Added water to fresh tank cleared lines and checked for hot water everything worked properly. Replaced the black vinyl piece on the back of the camper it shrunk. Filled voids on 3 corners of the roof with black Dicor. Checked stove and microwave they worked properly. Checked ac and furnace they work properly. Awning fabric was good. Made a adjustment to the regulator. Everything works properly.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: Hitch work

New hitch setup installation

CORRECTION: Had to move lp tanks forward to properly install the E2 hitch
Leveled the camper then checked the ball height and matched the truck. Connected the truck to the camper. Adjusted as needed. Connected the sway bars, 7way, breakaway cable, and safety chains.
Tightened all hardware.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



Customer #: 55792
GALMICHE, RAYMOND

14-1641 1000# E2 TRUNION HITCH W/BALL 1.00 N/C N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #E2: 0.00

Job #1 - Warranty

COMPLAINT: THERE ARE VOIDS IN THE DICOR ON THE ROOF THAT NEEDS TO BE TOUCHED UP.

CAUSE: Final pdi

CORRECTION: Voids in 3 corners of the roof. Filled with black Dicor non sag

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	54.00

Parts

Part #	Description	Qty	Price	Total
3388	551LSB-1 BLACK NON SAG DICOR	1.00	8.43	8.43

Subtotal for Job #1: 62.43

Parts Total: 8.43
Labour Total: 54.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 62.43

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 May 2025

W/O: 76743
Promised Date: 15 MAY 25



Customer #: 55792
GALMICHE, RAYMOND

